

Technical Appendix:
Section 3. BMP Effectiveness

Page left intentionally blank

Table of Contents

| | |
|-----------------------------------------------------------------------------|-----------|
| TA-3.1 2008 BMP Monitoring Status..... | 1 |
| SPA projects and BMP monitoring requirements..... | 1 |
| TA-3.2 Water Quality Monitoring | 7 |
| Completed projects and monitoring dates..... | 7 |
| TA-3.2.1 Stream Temperature..... | 11 |
| TA-3.2.2 Embeddedness | 11 |
| TA-3.2.3 Groundwater Levels | 11 |
| <i>Timbercreek (Clarksburg SPA).....</i> | <i>11</i> |
| TA-3.2.5 Instream Chemistry | 15 |
| TA-3.2.6 Continuous Stream Flow | 15 |
| TA-3.2.7 Cross Sections..... | 15 |
| <i>All Souls Cemetery (Clarksburg SPA)</i> | <i>16</i> |
| TA-3.2.8 Best Management Practice Sampling..... | 18 |
| <i>Route 29 / Briggs Chaney Road (Upper Paint Branch SPA).....</i> | <i>18</i> |
| TA-3.3. Sediment and Erosion Control (S&EC) BMP Monitoring | 21 |
| Evaluation of BMP Efficiency Using Percent Removal..... | 21 |
| TA-3.3.1. Grab Samples | 22 |
| TA-3.3.2. Flow-weighted Composite TSS Sampling | 25 |
| Automated Sampling Results..... | 25 |
| Sediment Basin #3 Clarksburg Town Center (Clarksburg SPA)..... | 27 |
| Sediment Basin #2 Gateway Commons (Clarksburg SPA)..... | 30 |
| Stringtown Rd. Extension Sediment Basin #3 (Clarksburg SPA)..... | 33 |
| TA-3.4. Stormwater Management (SWM) BMP Monitoring..... | 37 |
| Stormwater Treatment Trains in SPAs | 37 |
| TA-3.4.1 Surface Sand Filter | 37 |
| Background | 37 |
| Willow Oaks (Piney Branch SPA) | 39 |
| Snider's Estates (Upper Paint Branch SPA) | 47 |
| TA-3.4.2 Stormceptor® Results..... | 50 |
| Background | 50 |
| Cloverly Safeway (Upper Paint Branch SPA)..... | 51 |
| TA-3.5 Discussion of SPA BMP Effectiveness..... | 55 |
| Note to Reader..... | 55 |
| Literature Cited | 57 |

List of Figures

| | |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|
| Figure TA-3.1. Timbercreek property location and 2008 aerial image. | 12 |
| Figure TA-3.2. Timbercreek site plan and monitoring locations..... | 13 |
| Figure TA-3.3. All Souls Cemetery site plan and monitoring locations | 16 |
| Figure TA-3.4. All Souls Cemetery cross section 4616-4617 | 17 |
| Figure TA-3.5. All Souls Cemetery cross section 4612-4615 | 17 |
| Figure TA-3.6. 2008 aerial image and approximate boundaries of US Route 29 and Briggs Chaney Road interchange and road improvements..... | 18 |
| Figure TA-3.7. SWM Pond B photos: A) Overflow structure, B) View inside the outfall pipe, C) Looking downstream of the outfall | 19 |
| Figure TA-3.8. Clarksburg Town Center 2008 aerial and monitoring locations..... | 27 |
| Figure TA-3.9. Plan view of Clarksburg Town Center Sediment Basin #3 | 28 |
| Figure TA-3.10. Gateway Commons site plan (proposed) and monitoring locations | 30 |
| Figure TA-3.11. Plan view and sampling locations of Gateway Commons Sediment Basin #2 | 31 |
| Figure TA-3.12. 2008 aerial image of Stringtown Road Extension and Gateway Commons. | 33 |
| Figure TA-3.13. Plan view and sampling locations of Stringtown Rd. Extension Sediment Basin #3 | 35 |
| Figure TA-3.14. Enlargement of a section of the 2007 LiDAR image of Greenway Village Development (Newcut Road Neighborhood) showing the redundant water quality and quantity SWM BMPs designed to mitigate imperviousness impacts. ... | 38 |
| Figure TA-3.15. Aerial image of Willow Oaks sand filters. | 39 |
| Figure TA-3.16. Plan view of Willow Oaks BMP with monitoring locations (3) denoted | 40 |
| Figure TA-3.17. Hydrograph and rainfall for the Willow Oaks February 1, 2008 storm | 42 |
| Figure TA-3.18. 2008 aerial image of Snider's Estates..... | 47 |
| Figure TA-3.19. Snider's Estates stormwater management facility structure and drainage area detail | 48 |
| Figure TA-3.20. Plan view of Snider's Estates SWM with marked sampling locations.. | 48 |
| Figure TA-3.21. 2008 aerial image of Cloverly Safeway..... | 51 |
| Figure TA-3.22. Diagram of Cloverly Safeway SWM BMPs with marked sampling locations (2) | 52 |

List of Tables

| | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|
| Table TA-3.1. 2008 SPA project status with monitoring requirements. | 1 |
| Table TA-3.2. Updates and modifications to SPA BMP project monitoring requirements. | 5 |
| Table TA-3.3. Years of monitoring and data collected for completed SPA projects. | 7 |
| Table TA-3.4. Details for Timbercreek groundwater monitoring wells. | 12 |
| Table TA-3.5. Chemical parameters, methods, and reporting limits for groundwater chemistry monitoring at the Clarksburg Detention Center (Clarksburg SPA). | 14 |
| Table TA-3.6. Chemical parameters, methods, and detection limits for groundwater chemistry monitoring at the Boverman Property (Piney Branch SPA). | 14 |
| Table TA-3.7. Stream chemistry monitoring at Sheep's Run on the Snider Property (Piney Branch SPA). | 15 |
| Table TA-3.8. Construction timeline for Briggs Chaney Road and US 29 interchange and road improvements (Upper Paint Branch SPA). | 19 |
| Table TA-3.9. TSS results with flow rates and rainfall from 2003 to 2007 monitoring for Briggs Chaney Road and US 29 interchange and road improvements (Upper Paint Branch SPA). | 20 |
| Table TA-3.10. 2008 Total suspended solid (TSS) grab sample data used to calculate median removal efficiency. | 22 |
| Table TA-3.11. Sediment and Erosion Control structure information for three sediment basins monitored in Clarksburg. | 25 |
| Table TA-3.12. TSS sampling data for three Sediment and Erosion Control structures in Clarksburg (automated sampling). | 26 |
| Table TA-3.13. Clarksburg Town Center monitoring. | 27 |
| Table TA-3.14. TSS concentration results (mg/L) for flow-weighted composite sampling of Sediment Basin #3 at Clarksburg Town Center. | 29 |
| Table TA-3.15. Gateway Commons monitoring. | 30 |
| Table TA-3.16. Total suspended solids (TSS) monitoring at Gateway Commons Sediment Basin #2. | 32 |
| Table TA-3.17. Total suspended solids monitoring at Stringtown Rd. Extension Sediment Basin #3. | 34 |
| Table TA-3.18. Parameters and detection limits for Willow Oaks BMP monitoring. | 41 |
| Table TA-3.19. Characteristics of monitored storms at the Willow Oaks sand filters. | 41 |
| Table TA-3.21. Willow Oaks storm concentrations and loadings of nitrogen-based nutrients (nitrate, nitrite, total Kjeldahl nitrogen (TKN), total nitrogen). | 44 |
| Table TA-3.22. Willow Oaks storm concentrations and loadings of phosphorus-based nutrients (total phosphorus and orthophosphate) and total suspended solids (TSS). | 45 |
| Table TA-3.23. Storm events measured for flow exiting Snider's Estates SWM Pond 1. | 49 |
| Table TA-3.24. Detection limits and Maryland water quality standards for chemicals monitored at the Cloverly Safeway Stormceptor®. | 52 |
| Table TA-3.25. Characteristics of captured storms and measured flow as part of Cloverly Safeway SPA BMP monitoring. | 53 |
| Table TA-3.26. Storm concentrations and loadings of chemicals sampled at the Cloverly Safeway Stormceptor®. | 54 |

Page left intentionally blank

TA-3.1 2008 BMP Monitoring Status

SPA projects and BMP monitoring requirements

A list of all properties with SPA BMP monitoring is provided in Table TA-3.1. The first part of the table provides structural monitoring requirements; the second part of the table provides monitoring requirements for other parameters. Any modifications or updates to monitoring requirements are located in Table TA-3.2.

Table TA-3.1. 2008 SPA project status with monitoring requirements.

If structural monitoring was required, the type of sampling – grab or automated – is specified. “Automated” denotes that flow-weighted composite samples were collected using automated sampling equipment.

| SPA | No. | Project Name | Monitoring Phase (during 2008) | Structural Monitoring | |
|------------|-----|------------------------------------------|------------------------------------------------------------------------------|----------------------------------------|----------------------------------------------|
| | | | | S&EC Structure | SWM Structure |
| Clarksburg | 1 | All Souls Cemetery | Complete (2008) | No | No |
| | 2 | Cabin Branch | Pre-construction (construction anticipated 2010) | Yes - Automated | Yes - Automated |
| | 3 | Catawba Manor | Complete (2008) | No | No |
| | 4 | Clarksburg Detention Center (Jail) | Complete (2003) | Yes - Grab | No - Requirement dropped |
| | 5 | Clarksburg Ridge | Post Construction | Yes - Grab | Yes - Automated |
| | 6 | Clarksburg Town Center | During Construction; nearing post construction | Yes - Automated | Yes - Automated |
| | 7 | Clarksburg Village (w/Greenway Trail) | During Construction; nearing post construction for Phase I | Yes - Grab | Yes - Automated; 3 structures |
| | 8 | Eastside | Pre-construction; on hold | Yes - Automated | Yes - Automated |
| | 9 | Garnkirk Farms | Pre-construction; on hold | Yes - Automated | Yes - Automated |
| | 10 | Gateway 270 | Complete (2003) | No | No |
| | 11 | Gateway 270 Lot 7 | Complete (2005) | No | No |
| | 12 | Gateway 270 West | Complete (2004) | No | Yes - Automated; existing pond outfall |
| | 13 | Gateway Commons | During Construction | Yes - Automated | Yes - Automated |
| | 14 | Greenway Village | During Construction; nearing post- construction for Phases I and II | Yes - Grab&Auto * (2 structures) | Yes - Automated; 2 structures |
| | 15 | Highlands at Clarksburg | During Construction; nearing post construction i | Yes - Grab | Yes - Automated |
| | 16 | Martens ^a | During Construction; nearing post | Yes - Grab | Yes - Automated |
| | 17 | Parkside | During Construction (post construction in 2009) | Yes - Grab | No - Not required; Temperature only |
| | 18 | Running Brook Acres | Post Construction | Yes - Grab | Yes - Automated * |
| | 19 | Stringtown Road Extension | During Construction | Yes - Automated | Yes - Automated |

| | | | | | |
|------------------|----|---------------------------------------|-----------------------------------------------------------------------|---------------------------------|---------------------------------|
| | 20 | Summerfield Crossing | During Construction; nearing post construction (late 2009/early 2010) | No - Required but not sampled | Yes - Automated |
| | 21 | Tapestry | Pre-construction; on hold | Yes - Automated | Yes - Automated |
| | 22 | Timbercreek | Completed (2008) | No | No |
| | 23 | Woodcrest | During Construction | Yes-Grab & Auto* | Yes - Automated |
| Paint Branch | 24 | Briarcliff Manor West | Complete (2006) | No | No |
| | 25 | Briarcliff Meadows North & South | During Construction (post construction in 2009) | No | Yes - Automated; 2 structures |
| | 26 | Briggs Chaney Rd. / US 29 Interchange | Complete (2008) | Yes - Grab; outfall only | Yes - Grab; outfall only |
| | 27 | Cloverly Safeway | Complete (2008) | No | Yes - Automated |
| | 28 | Fairland Community Center | Complete (2003) | No | No |
| | 29 | Fairland Gardens | Complete (2000) | No | No |
| | 30 | Forest Ridge ^c | Post Construction | Yes - Grab | No |
| | 31 | Hunt Lions Den | Post Construction | No | No |
| | 32 | Parr's Ridge ^d | Complete (2005) | No | No |
| | 33 | Snider's Estates | Complete (2008) | Yes - Grab | Yes - Flow only |
| Piney Branch | 34 | Boverman | Complete (2004) | No | No |
| | 35 | Bruck | Complete (2003) | No | No |
| | 36 | Cavanaugh | Complete (2003) | No | No |
| | 37 | Peters Property | Complete (2004) | No | No |
| | 38 | Shady Grove Rd. | Complete (2002) | No | No |
| | 39 | Snider Property | Complete (2005) | No – stream chem. below outfall | No – stream chem. below outfall |
| | 40 | Traville | During Construction (post construction in 2009) | Yes - Grab | Yes - Automated |
| | 41 | Willow Oaks | Complete (2008) | No - Requirement dropped | Yes - Automated |
| Upper Rock Creek | 42 | Preserve at Rock Creek ^e | Pre-construction | No | Yes - Automated; 2 structures |
| | 43 | Reserve at Fair Hill ^f | During Construction | No | Yes - Automated; 3 structures |

^a Martens Property is divided into two phases, which are now called Glen at Hurley Ridge (Phase I) and the Meadows at Hurley Ridge (Phase II).

^b Summerfield Crossing is also referred to as Linthicum Property.

^c Forest Ridge is also known as Hunt Miles Tract or Fairland Farms

^d Parr's Ridge was previously known as Drayton Farms

^e The Preserve at Rock Creek was previously known as the Casey Property @ Bowie Mill.

^f The Reserve at Fair Hill was previously known as the Freeman Property.

* Automated (flow-weighted composite) sampling required, but some grab samples have been obtained instead.

| | | | |
|--|--|--|-------------------------------|
| | | | Other Monitoring Requirements |
|--|--|--|-------------------------------|

[illegible]

| | | | | | | | | | | | | |
|------------------|----|---------------------------|---|---|---|---|---|---|---|---|---|---|
| | 27 | Cloverly Safeway | | | | | | | | 1 | | |
| | 28 | Fairland Community Center | 2 | | | | | | | 3 | 1 | |
| | 29 | Fairland Gardens | | | | 1 | | | | | | |
| | 30 | Forest Ridge | 4 | | | | 3 | 1 | | 2 | 1 | 1 |
| | 31 | Hunt Lions Den | 3 | | | | 5 | 1 | | 2 | | |
| | 32 | Parr's Ridge | 1 | | | | | | | | | |
| | 33 | Snider's Estates | | | | | | | | | | |
| Piney Branch | 34 | Boverman | 1 | 1 | | | | 1 | | 1 | | |
| | 35 | Bruck | | | | | | 1 | | 2 | | |
| | 36 | Cavanaugh | 2 | | | | | 1 | | 3 | | |
| | 37 | Peters Property | | | | 1 | | 2 | | 2 | 1 | |
| | 38 | Shady Grove Rd. | | | | | | 4 | | | | |
| | 39 | Snider Property | | | 1 | | | | | | 1 | |
| | 40 | Traville | 3 | | | 1 | 4 | 1 | | 2 | | |
| Upper Rock Creek | 41 | Willow Oaks | | | | | | | | | | |
| | 42 | Preserve at Rock Creek | 4 | 4 | | | 3 | | 3 | | | |
| | 43 | Reserve at Fair Hill | 4 | 4 | | | 2 | | 2 | | | 1 |

^a GW = Groundwater

^b WQ = Water Quality; also known as "instream chemistry" or "surface water chemistry".

Table TA-3.2. Updates and modifications to SPA BMP project monitoring requirements.

| SPA | Project | Parameter | Reason | Comment |
|--------------|-----------------------------|--------------------|-----------------------------------------|----------------------------------------------------------------|
| Clarksburg | Catawba Manor | GW Level | Sampling not completed as specified | |
| Clarksburg | Clarksburg Detention Center | SWM BMP sampling | Discontinued | Requirement dropped |
| Clarksburg | Clarksburg Town Center | GW Level | Wells were never installed | To pick up additional post-construction monitoring of SWM BMPs |
| Clarksburg | Summerfield Crossing | S&EC grab sampling | Sampling not completed as specified | To pick up additional post-construction monitoring of SWM BMPs |
| Clarksburg | Summerfield Crossing | GW Level | Reduction from 5 wells to 3 | 2 wells abandoned |
| Paint Branch | Briarcliff Manor West | Continuous flow | Staff plate causing stream bank erosion | Monitoring discontinued; Requirement dropped |
| Paint Branch | Fairland Gardens | Continuous flow | Equipment failure and lack of data | Monitoring discontinued |
| Piney Branch | Traville | Stream WQ | Sampling not completed as specified | To pick up additional post-construction monitoring of SWM BMPs |
| Piney Branch | Willow Oaks | S&EC grab sampling | Structure deemed unsampleable | Requirement dropped; small property so no alternates available |

Page left intentionally blank

TA-3.2 Water Quality Monitoring

Completed projects and monitoring dates

Monitoring dates and requirements for completed projects are provided in Table TA-3.3. Table TA-3.3 is also split into two parts: the first part displays years of monitoring and structural monitoring requirements; the second part lists number of stations monitored for other parameters.

Table TA-3.3. Years of monitoring and data collected for completed SPA projects.

| | | | | Structural Monitoring | |
|--------------|---------------------------------------|-----------------------|---------------------------|--------------------------|-----------------------------------|
| SPA | Project Name | Year Monitoring Began | Year Monitoring Completed | S&EC Structure | SWM Structure |
| Clarksburg | All Souls Cemetery | 2001 | 2008 | No | No |
| Clarksburg | Catawba Manor | 1998 | 2008 | No | No |
| Clarksburg | Clarksburg Detention Center (Jail) | 1997 | 2003 | Yes - Grab | No- requirement dropped |
| Clarksburg | Gateway 270 | 1999 | 2003 | No | No |
| Clarksburg | Gateway 270 Lot 7 | 2003 | 2005 | No | No |
| Clarksburg | Gateway 270 West | 1999 | 2003 | No | Yes - grab; existing pond outfall |
| Clarksburg | Timbercreek | 2001 | 2008 | No | No |
| Paint Branch | Briarcliff Manor West /Baldi | 1998 | 2006 | No | No |
| Paint Branch | Briggs Chaney Rd. / US 29 Interchange | 2004* | 2008 | Yes - Grab; outfall only | Yes - Grab; outfall only |
| Paint Branch | Cloverly Safeway | 1998 | 2008 | No | Yes - Automated |
| Paint Branch | Fairland Community Center | 1998 | 2003 | No | No |
| Paint Branch | Fairland Gardens | 1997 | 2000 | No | No |
| Paint Branch | Parr's Ridge (Drayton Farms) | 1997 | 2005 | No | No |
| Paint Branch | Snider's Estates | 2004* | 2008 | Yes - Grab | Yes - flow only |
| Piney Branch | Boverman | 1998 | 2004 | No | No |
| Piney Branch | Bruck | 1998 | 2003 | No | No |
| Piney Branch | Cavanaugh | 1998 | 2003 | No | No |

| | | | | | |
|--------------|-----------------|--------|-------------|--------------------------------|--------------------------|
| Piney Branch | Peters Property | 1998 | 2004 | No | No |
| Piney Branch | Shady Grove Rd. | 1997 | 2002 | No | No |
| Piney Branch | Snider Property | 2000 | 2005 | Yes - Grab; outfall only | Yes - Grab; outfall only |
| Piney Branch | Willow Oaks | 2005** | 2008 | No - Requirement Dropped | Yes - Automated |

* - Preconstruction monitoring was not required as part of the monitoring plan. The first sample was collected in 2004 as part of during construction monitoring.

** - Preconstruction monitoring was not required as part of the monitoring plan. The requirement to sample TSS during construction was also dropped. The first sample was collected in 2005 as part of post construction monitoring.

Table 3.3. (continued). Years of monitoring and data collected for completed SPA projects. Numbers beneath headings indicate the number of stations monitored for the specified parameter.

| SPA | Project Name | Other Monitoring Requirements | | | | | | | | | | |
|--------------|--------------------------------------|-------------------------------|-------------------------|---------------------------|----------------------------|-----------------------------------|------------------|-------------------|-------------------|------------------|-------|------|
| | | GW ^a Lvl. | GW ^a Chem | Stream WQ ^b | Discrete Stream Flow | Cont- inuous Stream Flow | Cross Section | Embedded -ness | Stream Profile | Temp- erature | Photo | Rain |
| Clarksburg | All Souls Cemetery | | | | | | 2 | | | 1 | | |
| Clarksburg | Catawba Manor | 1 | | | | | | | | | | |
| Clarksburg | Clarksburg Detention Center (Jail) | 3 | 3 | | | 1 | | | | 1 | | 1 |
| Clarksburg | Gateway 270 | | | | | | | | | 4 | | |
| Clarksburg | Gateway 270 Lot 7 | | | | | | | | | | 1 | |
| Clarksburg | Gateway 270 West | | | | | | | | | | | |
| Clarksburg | Timbercreek | 2 | | | | | | | | 2 | | |
| Paint Branch | Briarcliff Manor West /Baldi | 1 | | | | 1 | 1 | 2 | | 3 | | |
| Paint Branch | Briggs Chaney Rd / US 29 Interchange | | | | | | | | | | | |
| Paint Branch | Cloverly Safeway | | | | | | | | | 1 | | |
| Paint Branch | Fairland Community Center | 2 | | | | | | | | 3 | 1 | |
| Paint Branch | Fairland Gardens | | | | | 1 | | | | | | |
| Paint Branch | Parr's Ridge (Drayton Farms) | 1 | | | | | | | | | | |
| Paint Branch | Snider's Estates | | | | | | | | | | | |
| Piney Branch | Boverman | 1 | 1 | | | | | 1 | | 1 | | |
| Piney Branch | Bruck | | | | | | | 1 | | 2 | | |
| Piney Branch | Cavanaugh | 2 | | | | | | 1 | | 3 | | |
| Piney Branch | Peters Property | | | | | 1 | | 2 | | 2 | 1 | |
| Piney Branch | Shady Grove Rd. | | | | | | | 4 | | | | |
| Piney Branch | Snider Property | | | 1 | | | | | | | 1 | |
| Piney Branch | Willow Oaks | | | | | | | | | | | |

^aGW = Groundwater; ^bWQ = Water Quality; also known as "instream chemistry".

Page left intentionally blank

TA-3.2.1 Stream Temperature

Stream water temperature is a very important factor in maintaining the biological health of streams. SPA BMP design features that help minimize temperature impacts include: 1) requiring enhanced stream buffers and reforestation, 2) minimizing imperviousness, 3) using dry ponds for runoff quantity control to avoid standing pools that soak up excessive heat, 4) promoting infiltration using roadside swales and other infiltration structures, and 5) using sand filters and biofiltration cells which cool warm water as it filters through sand and soil.

Stream temperature is logged continuously from June 1 through September 30 at a minimum of 24-minute intervals. It is monitored before development through the post-construction period to evaluate if BMPs meet performance goals by mitigating thermal impacts.

TA-3.2.2 Embeddedness

Embeddedness is monitored to evaluate the amount of sediment covering the stream bottom. SPA BMP monitoring of embeddedness documents existing instream fine sediment loads in riffle habitats and records changes in these fine sediment loads before, during, and after BMP installation. Quarterly data collection is most often required. Monitoring is in accordance with Montgomery County Department of Environmental Protection Protocols (1998).

TA-3.2.3 Groundwater Levels

Groundwater levels are monitored to determine if there are impacts to groundwater elevations and stream baseflow as a result of the development process. Furthermore, many SPA BMPs are designed to promote infiltration, so groundwater levels are often monitored upstream and downstream of the SWM facility. Discrete or continuous groundwater levels can be collected.

Timbercreek (Clarksburg SPA)

Timbercreek is an approximately 16.1-acre residential development. Two SWM facilities outfall approximately 250 and 350 feet up-gradient of Little Seneca Creek and an area of wetlands is present between the SWM outfalls and the creek. Two groundwater wells were monitored at Timbercreek to evaluate if impacts to the wetlands and baseflow of this portion of Little Seneca were mitigated. Monthly groundwater level monitoring was performed from 2001 through 2007. Two stream temperature stations were also monitored during this time period. Monitoring of pre-construction conditions occurred in 2001; post-construction monitoring commenced in 2004 and was required for three years.

An aerial image (Figure TA-3.1) and site plan of the Timbercreek development with well locations (Fig. TA-3.2) are provided. Well MW-1 is approximately 100 feet southwest

and down-gradient from SWM Facility 4. Well MW-2 is approximately 200 feet north and up-gradient from SWM Facility #6. Well details are provided in Table TA-3.4.




Figure TA-3.1. Timbercreek property location and 2008 aerial image.

Table TA-3.4. Details for Timbercreek groundwater monitoring wells.

| Well ID | County ID | State ID | Well Depth (ft bgs)* | Casing Exposed (ft) | Main Casing Type | Date Installed | Well Location |
|---------|-----------|------------|----------------------|---------------------|------------------|----------------|----------------------------|
| MW-1 | 241914 | MO-94-1836 | 15 | 1 | Plastic | 4/11/2001 | Down-gradient / Floodplain |
| MW-2 | 241914 | MO-94-1837 | 18.5 | 1.5 | Plastic | 4/11/2001 | Up-gradient / Upland |

*ft bgs = feet below ground surface




Figure TA-3.2. Timbercreek site plan and monitoring locations (GTA 2007).

TA-3.2.4 Groundwater Chemistry

In addition to effecting surface water, stormwater discharges may effect groundwater quality. The value of stormwater monitoring alone can be limited when assessing compliance with groundwater quality standards since stormwater quality is likely to change substantially while percolating through soils (Geosyntec Consultants and UWRRC 2002). Monitoring of groundwater chemistry in SPAs is often performed quarterly. Values are compared to Maryland water quality standards where values exist.

Three wells were monitored at Clarksburg Detention Center for the chemical parameters provided in Table TA-3.5. Nine samples were collected from November 1997 through September 2002. Pre-development monitoring was to last for six months, during construction monitoring until the site was stabilized and sediment control ponds were converted to stormwater management, and post-construction for three years.

Table TA-3.5. Chemical parameters, methods, and reporting limits for groundwater chemistry monitoring at the Clarksburg Detention Center (Clarksburg SPA).

| Parameter | Unit | Method | Detection Limit |
|-------------------------|----------|--------------------------|-----------------|
| Ammonia | mg/L | MCAWW 350.3 ⁺ | 0.100 |
| Nitrate | mg/L | MCAWW 353.2 | 2.50 |
| Total Kjeldahl Nitrogen | mg/L | MCAWW 351.3 | 0.100 |
| Total Phosphorous | mg/L | MCAWW 365.2 | 0.200 |
| Ortho-Phosphorous | mg/L | MCAWW 365.2 | 0.010 |
| Specific Conductance | umhos/cm | MCAWW 120.1 | 1.00 |
| pH | pH | MCAWW 150.1 | 0.010 |

⁺ MCAWW - Methods for Chemical Analysis of Water and Wastes

One well was monitored twice a year at the Boverman Property in the Piney Branch SPA for groundwater chemistry (Table TA-3.6). 10 samples were collected from July 1999 through October 2003.

Table TA-3.6. Chemical parameters, methods, and detection limits for groundwater chemistry monitoring at the Boverman Property (Piney Branch SPA).

| Parameter | Unit | Method | PQL [#] |
|-------------------------|------|-----------|------------------|
| Nitrate | mg/L | EPA 300.0 | 0.2 |
| Nitrite | mg/L | EPA 300.0 | 0.2 |
| Total Kjeldahl Nitrogen | mg/L | EPA 351.1 | 0.2 |
| Phosphorus | mg/L | EPA 365.3 | 0.05 |

[#] Practical Quantitation Limit

TA-3.2.5 Instream Chemistry

Stream chemistry was monitored on the Snider Property at one station on Sheep's Run near the outfall of SWM pond #1. Sheep's Run intersects the property and joins the Piney Branch just downstream of the Snider Property. Pre-construction monitoring began August 2000 with construction monitoring commencing December 2000. Post-construction began January 2003 and was required for three years. Grab sample data for stream chemistry monitoring at Sheep's Run is presented in Table TA-3.7.

Table TA-3.7. Stream chemistry monitoring at Sheep's Run on the Snider Property (Piney Branch SPA).

| Monitoring Period | Sample Date | TKN (mg/L) | Nitrate (mg/L) | Nitrite (mg/L) | TSS (mg/L) | Ortho-P (mg/L) | TP (mg/L) |
|-------------------|-------------|------------|----------------|----------------|------------|----------------|-----------|
| Pre | 8/30/2000 | 1.6 | 1.2 | ND* | 43.0 | 0.9 | 1.0 |
| | 9/27/2000 | 2.6 | 0.6 | 0.1 | 26.0 | 1.0 | 1.4 |
| | 10/11/2000 | 1.4 | 4.5 | ND* | 6.0 | 0.6 | 2.0 |
| During | 5/8/2001 | 2.4 | 1.1 | ND* | 35.0 | 0.2 | 0.7 |
| | 7/31/2001 | 1.0 | 0.9 | No Sample | 16.0 | No Sample | 0.3 |
| | 10/25/2001 | 1.0 | 1.0 | No Sample | 1.0 | No Sample | 2.1 |
| | 10/8/2002 | 1.1 | 0.3 | ND* | 9.0 | 0.7 | 2.2 |
| | 11/5/2002 | 0.6 | .03** | | 7.0 | 1.3 | 1.5 |
| Post | 5/27/2003 | 2.6 | 1.2 | ND* | 7.0 | 1.1 | 5.5 |
| | 10/14/2003 | 1.0 | 1.5 | ND* | 12.0 | 0.6 | 5.0 |
| | 6/16/2004 | 0.8 | 0.7** | | 17.0 | ND* | ND* |
| | 8/4/2004 | ND* | 0.6** | | 17.0 | ND* | ND* |
| | 9/21/2004 | 0.8 | 0.3** | | 16.0 | ND* | No Sample |
| | 6/9/2005 | ND* | 1.1 | ND* | 18.4 | ND* | ND* |
| | 8/3/2005 | 1.0 | 1.0 | ND* | 12.4 | ND* | No Sample |
| | 10/4/2005 | 0.5 | 0.7 | ND* | 46.4 | ND* | No Sample |

*Note: ND means Not Detected; results are less than the Practical Quantitation Limit (PQL).

The PQL for TKN is 0.1mg/L, for nitrate and nitrite 0.2mg/L, for ortho phosphate 0.1mg/L, and for TP 0.05mg/L.

**Note: Laboratory did not analyze sample for nitrate and nitrite separately, but rather combined them.

Additional Note: Property owner did not allow access to property for monitoring until October in 2002.

November monitoring was added for an additional data set. Access was also denied in July 2003.

Monitoring normally occurs in spring, summer, and fall of each year.

TA-3.2.6 Continuous Stream Flow

There are no technical appendix materials for this section.

TA-3.2.7 Cross Sections

Cross sections are used to document changes to the shape and area of the stream channel. Cross sections are installed and measured in accordance with Montgomery County Department of Environmental Protection BMP Monitoring Protocols (1998).

All Souls Cemetery (Clarksburg SPA)

Annual monitoring of two cross sections in Wildcat Branch (of Great Seneca Creek) downstream of the All Souls Cemetery began in 2002 and was completed in 2008. Both cross sections, as well as a temperature monitoring station, were located below (downstream of) the BMP outfall (Fig. TA-3.3). Plots submitted by the monitoring consultant, Macris, Hendricks, and Glasscock (MHG 2009) are provided for the upstream-most cross-section (4616-4617; Fig. TA-3.4) and the farthest downstream cross-section (4612-4615; Fig. TA-3.5).






Figure TA-3.3. All Souls Cemetery site plan and monitoring locations (MHG 2009). The stream flows approximately north (denoted as blue arrows) and monitoring stations are downstream of (below) the stormwater management pond outfall.



TA-3.2.8 Best Management Practice Sampling

Route 29 / Briggs Chaney Road (Upper Paint Branch SPA)

A new interchange was installed at the intersection of Briggs Chaney Road and US 29 in order to relieve traffic congestion along the two roads. This project included widening Briggs Chaney Road to accommodate two additional lanes west of the intersection, as well as widening and curb modifications to Old Columbia Pike (Fig. TA-3.6). A table of construction activities is provided in Table TA-3.8.




Figure TA-3.6. 2008 aerial image and approximate boundaries of US Route 29 and Briggs Chaney Road interchange and road improvements. The stormwater management pond monitored for TSS concentrations at the outfall is denoted.

TSS grab samples at the outfall of SWM Pond B (Fig. TA-3.7) were collected to monitor the structure's effectiveness while the roadway adjacent to the pond was restructured and widened. Grab samples were collected within 12 hours of the end of a rain event and at least one half hour apart. Water elevations in the outfall pipe were used to calculate flow. TSS grab sample data and flow values are provided in Table TA-3.9.

Table TA-3.8. Construction timeline for Briggs Chaney Road and US 29 interchange and road improvements (Upper Paint Branch SPA). Construction activities outside of SPA boundaries were not tracked (RKK 2009, J. Reel, personal communication)

| Date | Construction Activity |
|---------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| June 2004 | Project start up in SPA |
| | Installation of Sediment and Erosion Control (S&EC) * |
| | Some clearing |
| July - August 2004 | Utility relocations along Old Columbia Pike and Briggs Chaney Intersection |
| September 2004 | Installation of drainage structures along Briggs Chaney Road, within SPA |
| | Utility relocations within SPA (overhead and underground) |
| November 2004 | Briggs Chaney Rd. widening begins within SPA |
| | Water quality swale constructed (grated, matted, and seeded) |
| | Drainage structures completed |
| | Area temporarily seeded |
| December 2004 | Widening completed |
| December 2004 - November 2005 | <i>No activity within SPA until Nov. 2005 except for seeding / stabilization</i> |
| November - December 2005 | Sidewalks completed |
| | Utilities completed on west side of Briggs Chaney Rd. |
| April 2006 | SWM pocket sand filter installed on north side of Briggs Chaney Rd. |
| April - August 2006 | <i>No activity</i> |
| September 2006 | Concrete ditch removed, replaced with grass swale on south side of Briggs Chaney Rd. |
| | Completes work within SPA except for final paving |
| July 2007 | Entire project complete |
| * During construction super silt fence, inlet protection, and temporary stone outlet structures were used for S&EC. | |



Figure TA-3.7. SWM Pond B photos: A) Overflow structure, B) View inside the outfall pipe, C) Looking downstream of the outfall (RKK 2008).

Table TA-3.9.TSS results with flow rates and rainfall from 2003 to 2007 monitoring for Briggs Chaney Road and US 29 interchange and road improvements (Upper Paint Branch SPA).

| Monitoring Period | Sampling Event | Sampling Date | TSS (mg/L) | Flow * (cfs) | Rainfall (in) |
|------------------------------------------------------------------|----------------|------------------|------------|--------------|---------------|
| Pre-construction | 1 | July 23, 2003 | 5.0 | 1.01 | 2.15 |
| | | | 5.5 | 1.01 | |
| | | | 3.0 | 0.72 | |
| | 2 | March 16, 2004 | 17.0 | 0.02 | 0.19 |
| | | | 16.0 | 0.01 | |
| | | | 17.0 | 0.01 | |
| During Construction | 1 | July 27, 2004 | 2.4 | 0.17 | 0.52 |
| | | | 2.0 | 0.17 | |
| | | | 2.0 | 0.17 | |
| | 2 | December 8, 2004 | 45.0 | 0.5 | 0.27 |
| | | | 42.0 | 0.5 | |
| | | | 39.0 | 0.5 | |
| | 3 | May 25, 2005 | 7.0 | 0.03 | 0.3 |
| | | | 6.0 | 0.03 | |
| | | | 7.0 | 0.03 | |
| Post Construction | 1 | October 25, 2007 | 7.5 | 0.24 | 1.6 |
| | | | 5.0 | 0.24 | |
| | | | 5.5 | 0.24 | |
| * - Flow value calculated using water elevation in outfall pipe. | | | | | |

TA-3.3. Sediment and Erosion Control (S&EC) BMP Monitoring

Evaluation of BMP Efficiency Using Percent Removal

Using percent removal to evaluate BMP efficiency is a controversial topic. Two articles are most helpful regarding the topic: one that presents BMP efficiency in terms of percent removal (CWP 2007) and one that contests its use (Geosyntec Consultants and Wright Water Engineers 2007).

Copies of these documents are available online:

www.stormwater.net – Center for Watershed Protection. 2007. National pollutant removal performance database: version 3. (CWP 2007)

www.bmpdatabase.org – Frequently Asked Questions: Why does the International Stormwater BMP Database Project omit percent removal as a measure of BMP performance? (Geosyntec Consultants and Wright Water Engineers, Inc. 2007.)

Another document consulted when selecting the appropriate method to evaluate BMP efficiency can be located here:

<http://www.bmpdatabase.org/docs/Urban%20Stormwater%20BMP%20Performance%20Monitoring.pdf> – Urban Stormwater BMP Performance Monitoring: A Guidance Manual for Meeting the National Stormwater BMP Database Requirements (Geosyntec Consultants and UWRRC 2002).

Full citations are provided in the Literature Cited section at the end of this document.

TA-3.3.1. Grab Samples

113 total suspended solids (TSS) grab samples were collected and considered in efficiency analysis (Table TA-3.10). % Removal Efficiency = ([influent] - [effluent]) / [influent]).

Table TA-3.10. 2008 Total suspended solid (TSS) grab sample data used to calculate median removal efficiency. A negative removal efficiency indicates that more of a pollutant is leaving the system than is entering.

| SPA | Project and Structure | Project Phase | TSS Sampling Ongoing? | Sample Date | Inlet Conc. (average; (mg/L)) | Outfall TSS Conc. (mg/L) | TSS removal efficiency (%) | Rain (in.) | Rainfall Duration (hours) |
|------------|--------------------------------|---------------|-----------------------|-------------|-------------------------------|--------------------------|----------------------------|------------|---------------------------|
| Clarksburg | Clarksburg Ridge Sed. Trap C | Post | No | 4/12/2004 | 369 | 81.8 | 77.83% | 1.26 | |
| | | | | 7/7/2004 | 236 | 23.2 | 90.17% | 1.16 | |
| | | | | 8/2/2004 | 102 | 30 | 70.59% | 0.04 | |
| | Clarksburg Village - basin 'A' | During | No | 4/1/2004 | 406.67 | 53.33 | 86.89% | 1.45 | |
| | | | | 7/8/2004 | 72 | | 100.00% | 0.61 | |
| | | | | 9/9/2004 | 125 | | 100.00% | 0.52 | |
| | | | | 9/18/2004 | 96.67 | 213.33 | -120.68% | 1.34 | |
| | | | | 2/15/2005 | 53.33 | 27.33 | 48.75% | 0.49 | |
| | | | | 3/23/2005 | 357 | 284.67 | 20.26% | 1.29 | |
| | | | | 7/6/2005 | 95 | 78.33 | 17.54% | 0.77 | |
| | | | | 10/7/2005 | 25.33 | 146.67 | -479.02% | 0.99 | |
| | | | | 10/25/2005 | 2 | 10 | -400.00% | 1.09 | |
| | | | | 5/11/2006 | 20 | 33.33 | -66.67% | 0.91 | |
| | | | | 6/26/2006 | 2.23 | 5.8 | -160.09% | 2.03 | |
| | | | | 9/1/2006 | 3.27 | 3.17 | 3.16% | 1.41 | |
| | | | | 9/5/2006 | 7.73 | 18 | -132.86% | 1.24 | |
| | Clarksburg Village - basin 'B' | During | No | 4/1/2004 | 243 | 33.33 | 86.28% | 1.45 | |
| | | | | 7/8/2004 | 176 | 6 | 96.59% | 0.61 | |
| | | | | 9/9/2004 | 21.5 | 1.5 | 93.02% | 0.52 | |
| | | | | 9/18/2004 | 131.3333333 | 12.67 | 90.36% | 1.34 | |
| | | | | 2/15/2005 | 28.66666667 | 8.67 | 69.77% | 0.49 | |
| | | | | 3/23/2005 | 58.66666667 | 29.33 | 50.00% | 1.29 | |
| | | | | 7/6/2005 | 222.5 | 6.67 | 97.00% | 0.77 | |
| | | | | 10/7/2005 | 315.3333333 | | | 0.99 | |
| | | | | 10/25/2005 | 30.66666667 | 42.67 | -39.13% | 1.09 | |
| | | | | 5/11/2006 | 93.33333333 | 0 | 100.00% | 0.91 | |
| | | | | 6/26/2006 | 33.78333333 | 3.1 | 90.82% | 2.03 | |
| | | | | 9/1/2006 | 46.91666667 | 0.17 | 99.64% | 1.41 | |
| | | | | 9/5/2006 | 29.88333333 | 8.67 | 71.00% | 1.24 | |
| | Clarksburg Village Basin D | During | Yes | 8/21/2007 | 10.0835 | 7.83 | 22.35% | 0.93 | 0.95 |
| | | | | 9/11/2007 | 4.335 | | | 0.36 | 1.98 |
| | | | | 9/28/2007 | 3.13 | 4 | -27.80% | 0.6 | 5.08 |

| | | | | | | | | | |
|--|------------------------------------|--------|------|------------|-------------|--------|----------|------|-------|
| | | | | 11/27/2007 | 5.8665 | 7.9 | -34.66% | 0.56 | 6 |
| | | | | 4/22/2008 | 32.25 | 43.33 | -34.37% | 0.41 | 5.25 |
| | | | | 4/29/2008 | 4.9985 | 32 | -540.19% | 0.47 | 10 |
| | | | | 5/9/2008 | 2.45 | 1.67 | 31.96% | 0.82 | 16 |
| | | | | 5/16/2008 | 15.167 | 12.33 | 18.69% | 0.69 | 15.75 |
| | Clarksburg Village Basin F | During | Yes | 8/21/2007 | 68.94333333 | 3 | 95.65% | 0.93 | 0.95 |
| | | | | 9/11/2007 | 10.22233333 | 6.67 | 34.78% | 0.35 | 1.98 |
| | | | | 9/28/2007 | 9.68879 | 3.77 | 61.12% | 0.6 | 5.08 |
| | | | | 10/26/2007 | 184.5889 | 18.23 | 90.12% | 0.83 | 2 |
| | | | | 4/22/2008 | 178.332 | 489.67 | -174.58% | 0.41 | 5.25 |
| | | | | 4/29/2008 | 290.999 | 54.67 | 81.21% | 0.47 | 5 |
| | | | | 5/9/2008 | 179.4446667 | 22.33 | 87.55% | 0.82 | 16 |
| | | | | 5/16/2008 | 139.4446667 | 136 | 2.47% | 0.69 | 15.75 |
| | Glen at Hurley Ridge Basins 1 & 3 | During | No | 3/18/2004 | 12.6 | 4.6 | 63.49% | 0.16 | |
| | | | | 6/14/2004 | 15 | 4 | 73.33% | 0.83 | |
| | | | | 9/29/2004 | 47.25 | 156 | -230.16% | 2.05 | |
| | | | | 12/10/2004 | 10.7 | 80 | -647.66% | 0.98 | |
| | | | | 2/15/2005 | 8.4 | 41 | -388.10% | 0.47 | |
| | | | | 6/23/2005 | 11.35 | 4.8 | 57.71% | 0.35 | |
| | Glen at Hurley Ridge Traps B1 & B2 | During | No | 10/25/2005 | 207 | 118 | 43.00% | | |
| | | | | 4/4/2006 | 1020 | NS | | | |
| | | | | 5/12/2006 | 94 | 73 | 22.34% | | |
| | | | | 9/6/2006 | 54 | 38.4 | 28.89% | | |
| | | | | 10/18/2006 | 14.8 | 8.4 | 43.24% | | |
| | | | | 2/26/2007 | 274 | 18.2 | 93.36% | 0.72 | |
| | | | | 6/4/2007 | | 27 | | 0.54 | |
| | | | | 8/21/2007 | 6 | 83 | 1283.33% | 0.59 | |
| | Greenway Village Sed. Trap #5 | During | No | 6/29/2005 | 46.2 | 30 | 35.06% | 0.57 | |
| | | | | 7/8/2005 | 109.3333333 | 150 | -37.20% | 2.5 | |
| | | | | 7/15/2005 | 30 | 60 | -100.00% | 0.68 | |
| | | | | 10/8/2005 | 17.33333333 | 12 | 30.77% | 1.95 | |
| | | | | 9/5/2006 | 8.8 | 7.8 | 11.36% | 1.4 | |
| | | | | 9/14/2006 | 3.333333333 | 5 | -50.00% | 0.74 | |
| | | | | 10/17/2006 | 23.83333333 | 46.7 | -95.94% | 0.88 | |
| | Greenway Village Sed. Trap #7/7A | During | Yes* | 8/20/2007 | 99.5 | 9 | 90.95% | 1.11 | |
| | | | | 10/26/2007 | 192.6666667 | 46 | 76.12% | 1.57 | |
| | Highlands at Clarksburg - Basin 3 | During | Yes | 9/29/2004 | 104.7 | 264 | -152.23% | | |
| | | | | 12/10/2004 | 203.7 | 266 | -30.61% | | |
| | | | | 2/15/2005 | 32.7 | 30 | 8.16% | | |
| | | | | 6/23/2005 | 49.2 | 11.8 | 76.02% | | |
| | | | | 9/15/2005 | 65 | | | | |
| | | | | 10/25/2005 | 68.7 | 83 | -20.76% | | |
| | | | | 4/4/2006 | 134 | 139 | -3.73% | 0.39 | |
| | | | | 5/12/2006 | 205 | 106 | 48.29% | 0.91 | |

| | | | | | | | | | |
|--------------|-------------------------------------|----------|-------|------------|-------|------|----------|------|-------|
| | | | | 9/6/2006 | 17.8 | 96 | -439.33% | 1.23 | |
| | | | | 10/18/2006 | 9.5 | 25.2 | -164.34% | 0.71 | |
| | | | | 2/26/2007 | 27.2 | 34.2 | -25.74% | 0.69 | |
| | | | | 6/4/2007 | 3 | 4 | -33.33% | 0.54 | |
| | | | | 8/21/2007 | 12.7 | 4 | 68.42% | 0.59 | |
| | | | | 11/16/2007 | 10.7 | 1 | 90.63% | 0.57 | |
| | | | | 3/5/2008 | 133.3 | 28 | 79.00% | | |
| | | | | 4/29/2008 | 24.3 | 10 | 58.90% | | |
| | Parkside Cell #1 & Cell #2 | Post | No | 9/17/2004 | 250 | 330 | -32.00% | 1.34 | |
| | | | | 9/28/2004 | 170 | 120 | 29.41% | 1.83 | |
| | | | | 6/30/2005 | 5 | 5 | 0.00% | 0.58 | |
| | | | | 7/15/2005 | 8 | 4 | 50.00% | 0.75 | |
| | Running Brook | Post | No | 3/26/2002 | 23 | 18 | 21.74% | 0.56 | |
| | | | | 6/7/2002 | 58 | 12 | 79.31% | 0.27 | |
| | | | | 10/11/2002 | 100 | 104 | -4.00% | 1.6 | |
| | | | | 2/4/2003 | 520 | 226 | 56.54% | 0.4 | |
| | | | | 5/16/2003 | 53 | 410 | -673.58% | 0.85 | |
| | | | | 9/3/2003 | 8.5 | 8 | 5.88% | 0.31 | |
| | Woodcrest | During | Yes** | 9/5/2006 | 598 | 922 | -54.18% | 1.57 | |
| | | | | 9/14/2006 | 154 | 254 | -64.94% | 0.8 | |
| | | | | 10/17/2006 | 222 | 384 | -72.97% | 1.1 | |
| | | | | 8/20/2007 | 138 | 90 | 34.78% | 1.04 | |
| Paint Branch | Forest Ridge Cells #1 & #2 | Post | No | 9/3/2003 | 120 | | | 0.12 | |
| | | | | 9/4/2003 | 400 | | | 0.37 | |
| | | | | 9/23/2003 | 356 | 80 | 77.53% | 2.14 | |
| | | | | 4/1/2004 | 140 | 5 | 96.43% | 1.45 | |
| | | | | 4/13/2004 | 60 | 82 | -36.67% | 1.37 | |
| | | | | 7/8/2004 | 132 | 8 | 93.94% | 0.76 | |
| | | | | 9/9/2004 | 136 | 25.3 | 81.40% | 0.4 | |
| | | | | 9/18/2004 | 230 | | | 1.21 | |
| | | | | 2/15/2005 | 6 | 16 | -166.67% | 0.5 | |
| | | | | 3/23/2005 | 32 | 158 | -393.75% | 2.1 | |
| | | | | 7/8/2005 | 12 | 102 | -750.00% | 2.92 | |
| | Snider Estates | Complete | No | 4/12/2004 | 100 | 46 | 54.00% | 1.25 | 22.75 |
| | | | | 4/23/2004 | 53 | 13 | 75.47% | 0.71 | 1.25 |
| | | | | 5/18/2004 | 21 | 9 | 57.14% | 1 | 0.75 |
| | | | | 7/22/2004 | 31 | 7 | 77.42% | 1.43 | 1.43 |

* Greenway Village Sediment Trap 7/7A is being monitored using flow-weighted composite sampling but grabs were collected instead.

** Construction at Woodcrest is ongoing but no monitoring was collected in 2008 due to lack of payment by the developer.

TA-3.3.2. Flow-weighted Composite TSS Sampling

Automated Sampling Results

The characteristics of the basins sampled are provided in Table TA-3.11. All sampling data produced from those basins and used in preparation of Figure 3.12 (in the main document) are provided in Table TA-3.12.

Table TA-3.11. Sediment and Erosion Control structure information for three sediment basins monitored in Clarksburg.

| Project | Structure | Structure Type | Drainage Area (acres) | Capacity (CF) | Oversized? |
|------------------------------|-----------|--------------------------|-----------------------|---------------|------------|
| Clarksburg Town Center | Basin 3 | Two forebays & Main Cell | 44.5 | 89,280 | N/A * |
| | Forebay F | | 10.6 | 45,036 | |
| | Forebay G | | 16.7 | 276,085 | |
| Gateway Commons | Basin 2 | Dual Cell | 4.6 | 21,068 | Yes |
| Stringtown Road Extension | Basin 3 | Single Bay/Cell | 12.9 | 58,071 | Yes |
| * - Information not provided | | | | | |

Table TA-3.12. TSS sampling data for three Sediment and Erosion Control structures in Clarksburg (automated sampling).

| Project and Structure | Structure Type | Sampling locations | Date of Event | Rainfall | | | TSS loadings (lbs) | | TSS Load Removal Efficiency | Discharge (cfs) | |
|------------------------------------|--------------------------|---------------------------------|---------------|--------------|----------------|-----------------|--------------------------|---------------------|-----------------------------|--------------------------|----------|
| | | | | Amount (in.) | Duration (hrs) | Return interval | Entering (Sum of Inlets) | Out | | Inflow (combined inlets) | Outfall |
| Clarksburg Town Center - Basin 3 * | Two forebays & Main Cell | 4 – 2 in East, 1 in West, 1 Out | 4/30/2005 | 0.82 | 22.25 | < 1 yr | 520.7 | 29.4 | 94% | 65488.4 | 57292.9 |
| | | | 5/19/2005 | 1.04 | 14.15 | < 1 yr | 366 | 43.2 | 88% | 43992.0 | 35813.4 |
| | | | 5/23/2005 | 0.84 | 29.25 | < 1 yr | 146 | 17.5 | 88% | 57025.0 | 38853 |
| | | | 5/11/2006 | 1.76 | 13 | < 1 yr | 342.1 | 196.7 | 43% | 24563.4 | 66577.8 |
| | | | 6/1/2006 | 0.45 | 9 | < 1 yr | 1180 | 37.1 | 97% | 64989.2 | 78096.6 |
| | | | 9/1/2006 | 1.95 | 31.58 | < 1 yr | 3.1 | 4.4 | -44% | 114413.1 | 114048.6 |
| | | | 12/22/2006 | 1.3 | 15.67 | < 1 yr | 108.4 | 14.3 | 87% | 32710.9 | 16393.2 |
| | | | 3/15/2007 | 2.09 | 47 | < 1 yr | 87.2 | 4.3 | 95% | 127003.4 | 83313.6 |
| Gateway Commons - Basin 2 | Dual Cell | 3 – 1 inflow, 1 mid, 1 out | 4/21/2006 | 1.11 | 40.67 | < 1 yr | 18 | n.a ** | 100% | 127,646.40 | n.a ** |
| | | | 5/11/2006 | 1.76 | 13 | < 1 yr | 10.6 | n.a ** | 100% | 37,628.40 | n.a ** |
| | | | 9/1/2006 | 1.95 | 31.58 | < 1 yr | 0.3 | n.a ** | 100% | 21,450.60 | n.a ** |
| | | | 9/28/2006 | 0.79 | 5.5 | < 1 yr | 2.4 | n.a ** | 100% | 6,084.60 | n.a ** |
| | | | 9/25/2008 | 1.88 | 62.25 | < 1 yr | 38.3 | 0.5 | 99% | 48,152.40 | 492.6 |
| | | | 12/16/2008 | 0.64 | 19.1 | < 1 yr | 9.9 | 0.5 | 95% | 43,015.40 | 1,002.70 |
| | | | 1/6/2009 | 1.5 | 24.92 | < 1 yr | 42 | 0.4 | 99% | 83,768.20 | 906 |
| Stringtown Rd Extension - Basin 3 | Single Bay/Cell | 2 – 1 in, 1 out | 9/1/2006 | 1.95 | 31.58 | < 1 yr | 1.51 | N.S. ^(b) | 100% | 7,852 | 1,402 |
| | | | 9/28/2006 | 0.79 | 5.5 | < 1 yr | 7.87 | N.S. ^(b) | 100% | 1,612 | 414 |
| | | | 3/15/2007 | 2.09 | 47 | < 1 yr | (a) | 2.09 | (a) | (a) | 10,872 |
| | | | 4/11/2007 | 0.84 | 7.42 | < 1 yr | 1.05 | 0.12 | 88.80% | 2,917 | 655 |
| | | | 6/28/2007 | 0.79 | 0.67 | < 1 yr | 75.48 | 0.03 | 99.96% | 3,457 | 269 |
| | | | 12/2/2007 | 0.57 | 8.33 | < 1 yr | 0.38 | 0.02 | 94.50% | 1,843 | 811 |

* Twelve storms total; only storms with valid flows & calculated loadings considered.

** No outflow

(a) Not calculated due to backwater in Station #1 pipe.

(b) N.S. denotes no samples taken due to low water levels in Station #2 pipe.

Sediment Basin #3 Clarksburg Town Center (Clarksburg SPA)

Monitoring requirements and the dates of monitoring for Clarksburg Town Center are provided in Table TA-3.13. The locations of monitoring stations in Clarksburg Town Center are provided in Fig. TA-3.8.

Table TA-3.13. Clarksburg Town Center monitoring.

| Monitoring Requirement | Dates of Construction Monitoring | | |
|-------------------------------------------------------------------------------|----------------------------------|---------------------|---------------------|
| | Pre | During | Post ^(a) |
| Annual stream water chemistry (baseflow and flow-weighted stormwater samples) | April 1997 – May 1998 | 5/2/2001 - present | n/a |
| Continuous flow data and stream stage | | 10/5/2000 - present | n/a |
| Instream temperature | | 9/28/2000 - present | n/a |
| Embeddedness | | 4/2005 - present | n/a |
| Cross sections | | | n/a |
| S&EC Basin (TSS) | Not required | 1/2005 to present | Not required |
| SWM BMP Efficiency | Not required | Not required | n/a |

(a) - Clarksburg Town Center is still in the construction phase and post-construction monitoring will not begin until S&EC structures are converted, as-builts are approved, and a post-construction stream monitoring bond has been posted.




Figure TA-3.8. Clarksburg Town Center 2008 aerial and monitoring locations.

Approximate consultant monitoring stations denoted in orange: TMP = Temperature; TMP, CF = Temperature & Continuous Flow; WQ = Surface Water Quality (stream chemistry); XS, EMB = Cross Section and Embeddedness.

Sediment Basin #3 (Fig. TA-3.9) on Burdett Avenue is monitored quarterly for TSS using flow-weighted composite sampling. Complete TSS concentrations (Table TA-3.14) are provided.




Figure TA-3.9. Plan view of Clarksburg Town Center Sediment Basin #3 (Jones 2007). Final monitoring stations (4) are indicated.

Table TA-3.14. TSS concentration results (mg/L) for flow-weighted composite sampling of Sediment Basin #3 at Clarksburg Town Center.

| Storm Number | Date of Rainfall | Rainfall (inches) | Rainfall Duration (hours) | Rainfall Return Interval | TSS Concentration (mg/L) | | | |
|--------------|------------------|-------------------|---------------------------|--------------------------|-----------------------------------|-----------------------------------|-------------------------------------|----------------------------------------|
| | | | | | Station 1 | Station 3 | Station 5 | Station 6 |
| | | | | | Inlet to East Forebay (Forebay G) | Inlet to West Forebay (Forebay F) | Outfall (initial round of sampling) | 48" Concrete Inlet to East Forebay (G) |
| 1 | 3/23/2005 | 2.11 | 14.75 | < 1 yr | 590 | 1300 | 420 | * |
| 2 | 3/27/2005 | 1.37 | 26.25 | < 1 yr | 1600 | 850 | 500 | * |
| 3 | 4/1/2005 | 1.93 | 26.00 | < 1 yr | 4,200 | 4,400 | 1,100 | * |
| 4 | 4/30/2005 | 0.82 | 22.25 | < 1 yr | 230 | 140 | 40 | 630 |
| 5 | 5/19/2005 | 1.04 | 14.15 | < 1 yr | 240 | N.S. | 94 | 670 |
| 6 | 5/23/2005 | 0.84 | 29.25 | < 1 yr | 160 | N.S. | 35 | 200 |
| 7 | 4/21/2006 | 1.11 | 40.67 | < 1 yr | 200 | N.S. | 28 | 40 |
| 8 | 5/11/2006 | 1.76 | 13.00 | < 1 yr | 1800 | 370 | 230 | 610 |
| 9 | 6/1/2006 | 0.45 | 9.00 | < 1 yr | 3000 | N.S. | 37 | 1400 |
| 10 | 9/1/2006 | 1.95 | 31.58 | < 1 yr | 12 | N.S. | 3 | 2 |
| 11 | 12/22/2006 | 1.30 | 15.67 | < 1 yr | 120 | 3700 | 68 | 74 |
| 12 | 3/15/2007 | 2.09 | 47.00 | < 1 yr | 17 | N.S. | 4 | 54 |

* - An additional inlet to the east forebay (Forebay G) was discovered after the third monitored storm (April 1, 2005)

N.S. denotes no samples taken due to low water levels in pipe.

Sediment Basin #2 Gateway Commons (Clarksburg SPA)

Monitoring requirements and the dates of monitoring are provided in Table TA-3.15. A site plan with monitoring stations in Gateway Commons provided in Fig. TA-3.10

Table TA-3.15. Gateway Commons monitoring.

| Monitoring Requirement | Monitoring dates ^(a) |
|------------------------------------|------------------------------------------------|
| Groundwater elevations; year-round | 1/30/2003 - present |
| Cross sections | |
| Instream temperature | 6/1/2003 - present |
| Continuous flow | 2/5/2003 - present |
| S&EC Basin (TSS); quarterly | 10/27/2005 - present; during construction only |
| SWM BMP Efficiency | n/a; post-construction only |

(a) - Gateway Commons is still under construction and post-construction monitoring will not begin until S&EC structures are converted, as-builts are approved, and a post-construction stream monitoring bond has been posted.




Figure TA-3.10. Gateway Commons site plan (proposed) and monitoring locations (Thompson 2008).

Sediment Basin #2 (Fig. TA-3.11) on Roberts Tavern Drive in Gateway Commons is monitored quarterly for TSS using flow-weighted composite sampling. Monitoring was conducted from April through October 2006. Construction began on February 12, 2005, but monitoring was delayed by the need to finalize the basin configuration and to direct overland flows to the basin. Construction activities ceased in March 2006 while an additional plan was reviewed.




Figure TA-3.11. Plan view and sampling locations of Gateway Commons Sediment Basin #2 (Jones 2009a).

Complete storm event information and TSS concentrations, loadings, and reductions (Table TA-3.16) are provided.

Table TA-3.16. Total suspended solids (TSS) monitoring at Gateway Commons Sediment Basin #2.

| Date of Event | Rainfall | | | TSS Concentration (mg/L) | | | TSS Loading (lbs) | | | TSS Load Reduction | | Discharge Volume (CF) | | |
|---------------|-------------|----------------|----------------------|---------------------------|------------|------------|-------------------|------------|------------|--------------------------|--------------------------|-----------------------|------------|------------|
| | Amount (in) | Duration (hrs) | Return Interval (yr) | Station #1 ^(a) | Station #2 | Station #3 | Station #1 | Station #2 | Station #3 | Station #1 to Station #2 | Station #1 to Station #3 | Station #1 | Station #2 | Station #3 |
| 4/21/2006 | 1.11 | 40.67 | < 1 | 11 | 57 | n.a. | 18 | 3.4 | n.a. | 81% | n.a. | 127646.40 | 4598.40 | n.a. |
| 5/11/2006 | 1.76 | 13 | < 1 | 22 | 19 | n.a. | 10.6 | 0.8 | n.a. | 92% | n.a. | 37628.40 | 3286.50 | n.a. |
| 9/1/2006 | 1.95 | 31.58 | < 1 | 1 | n.a. | n.a. | 0.3 | n.a. | n.a. | 100% | n.a. | 21450.60 | n.a. | n.a. |
| 9/28/2006 | 0.79 | 5.5 | < 1 | 31 | n.a. | n.a. | 2.4 | n.a. | n.a. | 100% | n.a. | 6084.60 | n.a. | n.a. |
| 9/25/2008 | 1.88 | 62.25 | < 1 | 62 | 150 | 80 | 38.3 | 9.9 | 0.5 | 74% | 99% | 48152.40 | 5161.20 | 492.6 |
| 12/16/2008 | 0.64 | 19.1 | < 1 | 18 | 150 | 38 | 9.9 | 37.1 | 0.5 | -273% | 95% | 43015.40 | 19251.20 | 1002.70 |
| 1/6/2009 | 1.50 | 24.92 | < 1 | 39 | 34 | 36 | 42 | 2 | 0.4 | 95% | 99% | 83768.20 | 4544.60 | 906 |
| mean | 1.38 | 28.15 | | 26 | 82 | 51 | 17.4 | 10.6 | 0.5 | 38% ^(c) | 98% | 52535.14 | 7368.38 | 800.43 |

^(a) Station locations provided in figure TA-3.11.
^(b) n.a. not applicable (no samples taken due to low water levels in pipe)
^(c) TSS load reduction of first cell increases to 90% when storm even on 12/16/2008 is excluded.

According to Jones (2009a):

“A paired Student’s t-test on the compiled data from seven storms showed that the reduction in loading that occurred between Station #1 and Station #2 was not statistically significant ($P=0.28$), probably because of the results of the December 2008 storm. When comparing Station #1 and Station #3 loading data, the Student’s paired t-test showed a significant ($P=0.03$) reduction.”

Paired Student’s T-Test

This statistical analysis is used to compare a set of quantitative data where the data points are related and paired – in this case **loadings in vs loadings out** during the same storm event.

Stringtown Rd. Extension Sediment Basin #3 (Clarksburg SPA)

No monitoring other than TSS during construction and pollutant removal efficiency post construction is required at this property. An aerial image of the site is provided (Fig. TA-3.12)




Figure TA-3.12. 2008 aerial image of Stringtown Road Extension and Gateway Commons.

Storm event TSS concentrations and loadings are provided in Table TA-3.17. The site plan and sampling locations for Stringtown Rd. Extension Sediment Basin #3 are provided (Fig. TA-3.13).


TSS sampling at the inlet and the outfall of Sediment Basin #3 took place from September 2006 through December 2007. Construction on the Stringtown Road Extension has been completed since November 2006, but Basin #3 will not be converted to SWM until construction is completed at Gateway Commons since the two properties both drain to this basin.

Table TA-3.17. Total suspended solids monitoring at Stringtown Rd. Extension Sediment Basin #3.

| Date of Event | Rainfall | | | TSS (mg/L) | | TSS loading (lbs) | | TSS Load Reduction | Discharge (CF) | |
|-------------------------------------------------------------------------------|-------------|----------------|----------------------|------------|---------------------|-------------------|---------------------|--------------------------|----------------|------------|
| | Total (in.) | Duration (hrs) | Return Interval (yr) | Station #1 | Station #2 | Station #1 | Station #2 | Station #1 to Station #2 | Station #1 | Station #2 |
| 9/1/2006 | 1.95 | 31.58 | < 1 | 15 | N.S. ^(b) | 1.51 | N.S. ^(b) | 100% | 7,852 | 1,402 |
| 9/28/2006 | 0.79 | 5.5 | < 1 | 380 | N.S. ^(b) | 7.87 | N.S. ^(b) | 100% | 1,612 | 414 |
| 3/15/2007 | 2.09 | 47 | < 1 | 23 | 15 | (a) | 2.09 | (a) | (a) | 10,872 |
| 4/11/2007 | 0.84 | 7.42 | < 1 | 28 | 14 | 1.05 | 0.12 | 88.80% | 2,917 | 655 |
| 6/28/2007 | 0.79 | 0.67 | < 1 | 1700 | 9 | 75.48 | 0.03 | 99.96% | 3,457 | 269 |
| 12/2/2007 | 0.57 | 8.33 | < 1 | 16 | 2 | 0.38 | 0.02 | 94.50% | 1,843 | 811 |
| mean | 1.17 | 16.75 | | 360 | 10 | 17.26 | 0.57 | 97% | 3536 | 2404 |
| (a) Not calculated due to backwater in Station #1 pipe | | | | | | | | | | |
| (b) N.S. denotes no samples taken due to low water levels in Station #2 pipe. | | | | | | | | | | |

According to Jones (2008a):

“A paired Student’s t-test on the compiled data from five of the six storms showed that the reduction in loading that occurred between Station #1 and Station #2 was not statistically significant ($P=0.30$), most likely because of the small number of samples.”



Page left intentionally blank

TA-3.4. Stormwater Management (SWM) BMP Monitoring

Stormwater Treatment Trains in SPAs

Various BMPs are combined in series or as part of a treatment train in order to maximize pollutant reduction and improve stormwater treatment performance. Redundant controls (treatment trains) are required for stormwater quality control in SPAs (Fig. TA-3.14).

TA-3.4.1 Surface Sand Filter

Background

For more information on surface sand filters, please consult the following suggested materials:

<http://permittingservices.montgomerycountymd.gov/permitting/docs/rev2005MCSF.pdf> - Montgomery County Sand Filter (MC DPS 2007)

<http://www.epa.gov/owm/mtb/sandfltr.pdf> – Fact Sheet Sand Filters (US EPA 1999a)

<http://www.epa.gov/nrmrl/pubs/600r04184/600r04184.pdf> - The Use of Best Management Practices (BMPs) in Urban Watersheds (US EPA 2004).

http://www.cwp.org/Resource_Library/Center_Docs/PWP/ELC_PWP105.pdf – Developments in Sand Filter Technology to Treat Stormwater Runoff. (T.R.S. 2002)

<http://www.fhwa.dot.gov/environment/ultraurb/3fs8.htm> –Fact Sheet – Surface Sand Filters (Shoemaker et al. 2002a)

http://www.metrocouncil.org/environment/Watershed/BMP/CH3_STFiltSurfSand.pdf – Chapter 3: Best Management Practices: Surface Sand Filters (Metropolitan Council & Barr Engineering Co. 2001)

Full citations are provided in the Literature Cited section at the end of this document.

Stormwater Treatment Train Clarksburg SPA




Figure TA-3.14. Enlargement of a section of the 2007 LiDAR image of Greenway Village Development (Newcut Road Neighborhood) showing the redundant water quality and quantity SWM BMPs designed to mitigate imperviousness impacts.

Willow Oaks (Piney Branch SPA)

An aerial and plan view of the Willow Oaks sand filters (two in series) are provided (Figs TA-3.15 and TA-3.16). BMP pollutant removal efficiency data was collected using flow-weighted composite sampling. Table TA-3.18 lists the parameters and detection limits for the Willow Oaks SWM BMP monitoring (Jones 2008b).




Figure TA-3.15. Aerial image of Willow Oaks sand filters.

The only other monitoring requirement at Willow Oaks was for TSS sampling during construction, but this requirement was dropped when the structure was deemed unsampleable. An alternate sediment basin could not be selected due to the relatively small development and level of disturbance.




Figure TA-3.16. Plan view of Willow Oaks BMP with monitoring locations (3) denoted (Jones 2008b).

Table TA-3.18. Parameters and detection limits for Willow Oaks BMP monitoring.

| Parameter | Detection Limit (mg/L) | Method | MD Freshwater Acute Criteria (mg/L)* |
|------------------------------------------------------------------------------------------------------------------------------------|------------------------|--------------------------|--------------------------------------|
| Cadmium | 0.0005 | EPA 200.8 | 0.002 |
| Copper | 0.002 | EPA 200.8 | 0.013 |
| Lead | 0.002 | EPA 200.8 | 0.065 |
| Zinc | 0.010 | EPA 200.8 | 0.12 |
| Nitrate | 0.02 | EPA 353.1 & SM 4500NO3-H | None |
| Nitrite | 0.02 | EPA 353.1 & SM 4500NO3-H | None |
| Total Kjeldahl Nitrogen (TKN) | 0.5 | EPA 351.3 & SM 4500NH3-C | None |
| Total Nitrogen | 0.02 | EPA 353.1 & SM 4500NO3-H | None |
| Total Suspended Solids (TSS) | 1.0 | EPA 160.2 & SM 2540 D | None |
| Total Phosphorus | 0.01 | EPA 365.2 & SM 4500P-E | None |
| Orthophosphate | 0.01 | EPA 365.2 & SM 4500P-E | None |
| * Water quality criteria for metals are based on dissolved forms; water chemistry data provided are for total metal concentration. | | | |

Monitored storm events (Table TA-3.19) and concentrations and loadings of pollutants from monitored storm events are presented (Tables TA-3.20 – TA-3.22). An estimated flow value was provided for the 2/1/2008 storm event (Table TA-3.19). An equipment failure caused a loss of flow data for a period. An integration below the curve of the hydrograph (Fig. TA-3.17) at the points where the unit cut off and regained function allowed for a calculated estimate. Furthermore, the hydrograph is usually relatively flat during other monitored storms at Station 3 / the downstream station (Jones 2008b; Jones 2009, personal communication).

Table TA-3.19. Characteristics of monitored storms at the Willow Oaks sand filters.

| Date of Event | Storm Characteristics | | | | Discharge Volume (m ³) | | |
|---------------|-----------------------|---------------------------|--------------------------|---------------------------|------------------------------------|----------------------|-----------------------|
| | Rain (in) | Rainfall Duration (hours) | Rainfall Return Interval | Preceding drying time (h) | Station #1 | Station #2 | Station #3 |
| 7/7/2005 | 2.59 | 14.5 | 1-2 | 42.25 | 5,712 | 6,440 ^(a) | 24,577 ^(b) |
| 10/24/2005 | 1.35 | 29.25 | < 1 | 46.5 | 4,660 | 981 | 15,396 ^(b) |
| 1/22/2006 | 0.8 | 14.5 | < 1 | 108.25 | 2,737 | 410 | 293 |
| 4/21/2006 | 1.51 | 26.75 | < 1 | 104.5 | 2,649 | 2,984 ^(a) | 269 |
| 9/28/2006 | 0.73 | 4.75 | < 1 | 98.5 | 636 | 34 | 1,497 ^(b) |
| 10/17/2006 | 0.74 | 9 | < 1 | 116.5 | 1,161 | 73 | 37 |
| 11/16/2006 | 1.6 | 7.75 | < 1 | 72 | 3,887 | 8,337 ^(a) | 99 |

| | | | | | | | |
|-------------------|------|-------|-----|--------|------|---------------------|--------------------|
| 4/11/2007 | 0.72 | 7.25 | < 1 | 105 | 723 | 57 | 85 |
| 12/15/2007 | 0.76 | 14.5 | < 1 | 36.17 | 1972 | 117 | 373 |
| 2/1/2008 | 1.3 | 7.92 | < 1 | 64.17 | 861 | 4202 ^(a) | 638 ^(c) |
| 3/4/2008 | 2.11 | 13.92 | < 1 | 168.17 | 616 | 869 ^(a) | 228 |
| 3/7/2008 | 0.67 | 27.5 | < 1 | 54.75 | 338 | 59 | 153 |
| 3/19/2008 | 0.56 | 13.83 | < 1 | 50.67 | 229 | 40 | 75 |

^(a) Inaccurate flow rate measurement due to ponding in weir (Station #2)

^(b) Inaccurate flow rate measurement due to bubble line misplacement or pinching (Station #3)

^(c) Discharge includes estimated amount




Figure TA-3.17. Hydrograph and rainfall for the Willow Oaks February 1, 2008 storm (Jones 2008b).

Table TA-3.20. Willow Oaks storm concentrations and loadings of metals. Loadings are not calculated if flow value is inaccurate and not presented if concentration was below the detection limit. A negative percent reduction indicates that more of pollutant is leaving the system than is entering.

| Storm Date | Cadmium | | | | Copper | | | | Lead | | | | Zinc | | | |
|--------------------------------------------------------------------------------------------------|----------------|-----------------|-----------------|------------------------|----------------------|----------------------|----------------------|------------------------|----------------|-----------------|-----------------|------------------------|----------------|---------------------|-----------------|------------------------|
| | Station 1 (In) | Station 2 (Mid) | Station 3 (Out) | Pol. Red. (In vs. Out) | Station 1 (In) | Station 2 (Mid) | Station 3 (Out) | Pol. Red. (In vs. Out) | Station 1 (In) | Station 2 (Mid) | Station 3 (Out) | Pol. Red. (In vs. Out) | Station 1 (In) | Station 2 (Mid) | Station 3 (Out) | Pol. Red. (In vs. Out) |
| Analytical Concentration (mg/L) and Pollutant Reduction (%) | | | | | | | | | | | | | | | | |
| 7/7/2005 | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.005 | 0.006 | 0.008 | -60.0% | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.022 | 0.021 | 0.023 | -4.5% |
| 10/24/2005 | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.009 | 0.01 | 0.006 | 33.3% | B.D.L. | B.D.L. | B.D.L. | n.c. | B.D.L. | 0.01 | 0.012 | n.c. |
| 1/22/2006 | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.011 | 0.008 | 0.011 | 0.0% | 0.0032 | B.D.L. | B.D.L. | n.c. | 0.0619 | 0.0221 | 0.0277 | 55.3% |
| 4/21/2006 | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.017 ^(b) | 0.012 | 0.01 | 41.2% | 0.004 | B.D.L. | B.D.L. | n.c. | 0.041 | 0.016 | 0.012 | 70.7% |
| 9/28/2006 | B.D.L. | 0.0007 | B.D.L. | n.c. | 0.021 ^(b) | 0.110 ^(b) | 0.015 ^(b) | 28.6% | 0.003 | 0.015 | B.D.L. | n.c. | 0.068 | 0.14 ^(b) | 0.028 | 58.8% |
| 10/17/2006 | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.008 | 0.008 | 0.009 | -12.5% | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.042 | 0.028 | 0.027 | 35.7% |
| 11/16/2006 | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.007 | 0.009 | B.D.L. | n.c. | 0.003 | B.D.L. | B.D.L. | n.c. | 0.054 | 0.048 | B.D.L. | n.c. |
| 4/11/2007 | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.0083 | 0.0093 | 0.0078 | 6.0% | 0.0023 | B.D.L. | B.D.L. | n.c. | 0.062 | 0.0446 | 0.0616 | 0.6% |
| 12/15/2007 | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.0058 | 0.01 | 0.0093 | -60.3% | B.D.L. | B.D.L. | B.D.L. | n.c. | B.D.L. | 0.021 | 0.041 | n.c. |
| 2/1/2008 | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.005 | 0.0074 | 0.0087 | -74.0% | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.018 | 0.012 | 0.017 | 5.6% |
| 3/4/2008 | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.0068 | 0.0092 | 0.0097 | -42.6% | 0.002 | B.D.L. | B.D.L. | n.c. | 0.027 | 0.013 | 0.014 | 48.1% |
| 3/7/2008 | B.D.L. | B.D.L. | 0.001 | n.c. | 0.008 | 0.009 | 0.0086 | -7.5% | 0.0023 | B.D.L. | B.D.L. | n.c. | 0.036 | 0.013 | 0.027 | 25.0% |
| 3/19/2008 | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.0086 | 0.0099 | 0.011 | -27.9% | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.03 | 0.012 | 0.025 | 16.7% |
| Pollutant Loadings (g) and Pollutant Reduction (%) | | | | | | | | | | | | | | | | |
| 7/7/2005 | n.c. | * | * | n.c. | 28.6 | * | * | n.c. | n.c. | * | * | n.c. | 125.7 | * | * | n.c. |
| 10/24/2005 | n.c. | n.c. | * | n.c. | 41.9 | 9.8 | * | n.c. | n.c. | n.c. | * | n.c. | n.c. | 9.8 | * | n.c. |
| 1/22/2006 | n.c. | n.c. | n.c. | n.c. | 30.1 | 3.3 | 3.2 | 89.3% | 8.8 | n.c. | n.c. | n.c. | 169.4 | 9.1 | 8.1 | 95.2% |
| 4/21/2006 | n.c. | * | n.c. | n.c. | 45 | * | 2.7 | 94.0% | 10.6 | * | n.c. | n.c. | 108.6 | * | 3.2 | 97.0% |
| 9/28/2006 | n.c. | 0.02 | * | n.c. | 13.4 | 3.8 | * | n.c. | 1.9 | 0.5 | * | n.c. | 43.3 | 4.8 | * | n.c. |
| 10/17/2006 | n.c. | n.c. | n.c. | n.c. | 9.3 | 0.6 | 0.3 | 96.4% | n.c. | n.c. | n.c. | n.c. | 48.8 | 2 | 1 | 97.9% |
| 11/16/2006 | n.c. | * | n.c. | n.c. | 27.2 | * | n.c. | n.c. | 11.7 | * | n.c. | n.c. | 209.9 | * | n.c. | n.c. |
| 4/11/2007 | n.c. | n.c. | n.c. | n.c. | 6 | 0.5 | 0.7 | 89.0% | 1.7 | n.c. | n.c. | n.c. | 44.9 | 2.5 | 5.2 | 88.4% |
| 12/15/2007 | n.c. | n.c. | n.c. | n.c. | 11.44 | 1.17 | 3.47 | 69.7% | n.c. | n.c. | n.c. | n.c. | n.c. | 2.5 | 15.3 | n.c. |
| 2/1/2008 | n.c. | * | 0.64 | n.c. | 4.31 | * | 5.55 | -28.8% | n.c. | * | n.c. | n.c. | 15.5 | * | 10.8 | 30.1% |
| 3/4/2008 | n.c. | * | n.c. | n.c. | 4.19 | * | 2.21 | 47.2% | 1.2 | * | n.c. | n.c. | 16.6 | * | 3.2 | 80.2% |
| 3/7/2008 | n.c. | n.c. | n.c. | n.c. | 2.71 | 0.53 | 1.32 | 51.4% | 0.8 | n.c. | n.c. | n.c. | 12.2 | 0.8 | 4.1 | 66.1% |
| 3/19/2008 | n.c. | n.c. | n.c. | n.c. | 1.97 | 0.39 | 0.82 | 58.1% | n.c. | n.c. | n.c. | n.c. | 6.9 | 0.5 | 1.9 | 72.7% |
| * - Loading not calculated due to inaccurate flow rate measurement | | | | | | | | | | | | | | | | |
| ^(b) At or above acute criteria value (Refer to Table TA-3.18) | | | | | | | | | | | | | | | | |
| B.D.L - Concentration (mg/L) below detection limit (Refer to Table TA-3.18) | | | | | | | | | | | | | | | | |
| n.c. - Not Calculated (if concentration was below detectable limit or flow value was inaccurate) | | | | | | | | | | | | | | | | |

Table TA-3.21. Willow Oaks storm concentrations and loadings of nitrogen-based nutrients (nitrate, nitrite, total Kjeldahl nitrogen (TKN), total nitrogen). Loadings are not calculated if flow value is inaccurate and not presented if concentration was below the detection limit. A negative percent reduction indicates that more of pollutant is leaving the system than is entering

| Storm Date | Nitrate | | | | Nitrite | | | | TKN | | | | Total Nitrogen | | | |
|--------------------------------------------------------------------|----------------|-----------------|-----------------|------------------------|----------------|-----------------|-----------------|------------------------|----------------|-----------------|-----------------|------------------------|----------------|-----------------|-----------------|------------------------|
| | Station 1 (In) | Station 2 (Mid) | Station 3 (Out) | Pol. Red. (In vs. Out) | Station 1 (In) | Station 2 (Mid) | Station 3 (Out) | Pol. Red. (In vs. Out) | Station 1 (In) | Station 2 (Mid) | Station 3 (Out) | Pol. Red. (In vs. Out) | Station 1 (In) | Station 2 (Mid) | Station 3 (Out) | Pol. Red. (In vs. Out) |
| Analytical Concentration (mg/L) and Pollutant Reduction (%) | | | | | | | | | | | | | | | | |
| 7/7/2005 | 0.1 | 0.06 | 0.08 | 20.0% | 0.02 | 0.02 | B.D.L. | n.c. | 1 | 1.2 | B.D.L. | n.c. | 1.1 | 1.3 | 0.08 | 92.7% |
| 10/24/2005 | 0.18 | 0.25 | 0.35 | -94.4% | B.D.L. | 0.02 | 0.02 | n.c. | 1 | 0.7 | 0.6 | 40.0% | 1.2 | 0.95 | 0.97 | 19.2% |
| 1/22/2006 | 0.24 | 0.2 | 0.14 | 41.7% | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.6 | 0.6 | 0.6 | 0.0% | 0.84 | 0.8 | 0.74 | 11.9% |
| 4/21/2006 | 0.46 | 0.47 | 0.63 | -37.0% | B.D.L. | 0.04 | 0.04 | n.c. | 1.6 | 1 | 0.7 | 56.3% | 2.1 | 1.5 | 1.4 | 33.3% |
| 9/28/2006 | 0.59 | 0.46 | 0.42 | 28.8% | 0.02 | 0.03 | 0.02 | 0.0% | B.D.L. | B.D.L. | 0.8 | n.c. | 0.61 | 0.49 | 0.52 | 14.8% |
| 10/17/2006 | 0.35 | 0.3 | 0.23 | 34.3% | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.7 | B.D.L. | B.D.L. | n.c. | 0.42 | 0.3 | 0.23 | 45.2% |
| 11/16/2006 | 0.25 | 0.15 | 0.23 | 8.0% | 0.02 | B.D.L. | B.D.L. | n.c. | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.27 | 0.15 | 0.23 | 14.8% |
| 4/11/2007 | 1.5 | 2.18 | 2.8 | -86.7% | 0.02 | 0.02 | B.D.L. | n.c. | 0.9 | B.D.L. | B.D.L. | n.c. | 2.4 | 2.2 | 2.8 | -16.7% |
| 12/15/2007 | 0.35 | 0.3 | 0.23 | 34.3% | B.D.L. | B.D.L. | B.D.L. | n.c. | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.35 | 0.3 | 0.23 | 34.3% |
| 2/1/2008 | 0.58 | 0.52 | 0.33 | 43.1% | B.D.L. | B.D.L. | B.D.L. | n.c. | 1 | 0.9 | 0.6 | 40.0% | 1.6 | 1.4 | 0.93 | 41.9% |
| 3/4/2008 | 0.43 | 0.52 | 0.35 | 18.6% | B.D.L. | B.D.L. | B.D.L. | n.c. | 4.1 | 3.2 | 2.8 | 31.7% | 4.5 | 3.7 | 3.2 | 28.9% |
| 3/7/2008 | 0.34 | 0.79 | 0.6 | -76.5% | B.D.L. | B.D.L. | B.D.L. | n.c. | 0.6 | 1.1 | 0.8 | 33.3% | 0.94 | 1.9 | 1.4 | -48.9% |
| 3/19/2008 | 0.3 | 0.4 | 0.34 | -13.3% | B.D.L. | B.D.L. | B.D.L. | n.c. | 1 | 0.6 | 0.7 | 30.0% | 1.3 | 1 | 1 | 23.1% |
| Pollutant Loadings (g) and Pollutant Reduction (%) | | | | | | | | | | | | | | | | |
| 7/7/2005 | 571.2 | * | * | n.c. | 114.2 | * | * | n.c. | 5712.2 | * | * | n.c. | 6283.5 | * | * | n.c. |
| 10/24/2005 | 838.8 | 245.3 | * | n.c. | n.c. | 19.6 | * | n.c. | 4660.1 | 686.9 | * | n.c. | 5592.1 | 932.2 | * | n.c. |
| 1/22/2006 | 656.9 | 82 | 41 | 93.8% | n.c. | n.c. | n.c. | n.c. | 1642.2 | 245.9 | 175.5 | 89.3% | 2299.1 | 327.9 | 216.5 | 90.6% |
| 4/21/2006 | 1218.6 | * | 169.3 | 86.1% | n.c. | * | 10.8 | n.c. | 4238.5 | * | 188.2 | 95.6% | 5563 | * | 376.3 | 93.2% |
| 9/28/2006 | 375.3 | 15.8 | * | n.c. | 12.7 | 1 | * | n.c. | n.c. | n.c. | * | n.c. | 388 | 16.9 | * | n.c. |
| 10/17/2006 | 406.4 | 21.8 | 8.6 | 97.9% | n.c. | n.c. | n.c. | n.c. | 812.8 | n.c. | n.c. | n.c. | 487.7 | 21.8 | 8.6 | 98.2% |
| 11/16/2006 | 971.9 | * | 22.8 | 97.7% | 77.7 | * | n.c. | n.c. | n.c. | * | n.c. | n.c. | 1049.6 | * | 22.8 | 97.8% |
| 4/11/2007 | 1085.2 | 124.6 | 237.1 | 78.1% | 14.5 | 1.1 | n.c. | n.c. | 651.1 | n.c. | n.c. | n.c. | 1736.2 | 125.8 | 237.1 | 86.3% |
| 12/15/2007 | 690.2 | 35.2 | 85.8 | 87.6% | n.c. | n.c. | n.c. | n.c. | n.c. | n.c. | n.c. | n.c. | 690.2 | 35.2 | 85.8 | 87.6% |
| 2/1/2008 | 499.6 | * | 210.5 | 57.9% | n.c. | * | n.c. | n.c. | 861.4 | * | 382.7 | 55.6% | 1378.3 | * | 593.2 | 57.0% |
| 3/4/2008 | 264.7 | * | 79.7 | 69.9% | n.c. | n.c. | n.c. | n.c. | 2524.3 | * | 637.5 | 74.7% | 2770.5 | * | 728.6 | 73.7% |
| 3/7/2008 | 115.1 | 46.4 | 91.8 | 20.2% | n.c. | n.c. | n.c. | n.c. | 203.1 | 64.6 | 122.4 | 39.7% | 318.1 | 111.6 | 214.2 | 32.7% |
| 3/19/2008 | 68.6 | 15.9 | 25.5 | 62.9% | n.c. | n.c. | n.c. | n.c. | 228.7 | 23.8 | 52.4 | 77.1% | 297.3 | 39.7 | 74.9 | 74.8% |

* - Loading not calculated due to inaccurate flow rate measurement

B.D.L - Concentration (mg/L) below detection limit (Refer to Table TA-3.18)

n.c. = Not Calculated (if concentration was below detectable limit or flow value was inaccurate)

Table TA-3.22. Willow Oaks storm concentrations and loadings of phosphorus-based nutrients (total phosphorus and orthophosphate) and total suspended solids (TSS). Loadings are not calculated if flow value is inaccurate and not presented if concentration was below the detection limit. A negative percent reduction indicates that more of pollutant is leaving the system than is entering.

| Storm Date | Total Phosphorus | | | | Orthophosphate | | | | TSS | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|--------------------|--------------------|------------------------|-------------------|--------------------|--------------------|------------------------|-------------------|--------------------|--------------------|------------------------|
| | Station 1 (In) | Station 2 (Mid) | Station 3 (Out) | Pol. Red. (In vs. Out) | Station 1 (In) | Station 2 (Mid) | Station 3 (Out) | Pol. Red. (In vs. Out) | Station 1 (In) | Station 2 (Mid) | Station 3 (Out) | Pol. Red. (In vs. Out) |
| Analytical Concentration (mg/L) and Pollutant Reduction (%) | | | | | | | | | | | | |
| 7/7/2005 | 0.07 | 0.07 | 0.06 | 14.3% | 0.04 | 0.04 | 0.03 | 25.0% | 20 | 5 | 16 | 20.0% |
| 10/24/2005 | 0.06 | 0.15 | 0.17 | -183.3% | 0.02 | 0.09 | 0.12 | -500.0% | 5 | 8 | 6 | -20.0% |
| 1/22/2006 | 0.11 | 0.11 | 0.1 | 9.1% | 0.03 | 0.03 | B.D.L. | n.c. | 18 | 10 | 24 | -33.3% |
| 4/21/2006 | 0.15 | 0.11 | 0.1 | 33.3% | 0.1 | 0.06 | 0.04 | 60.0% | 26 | 8 | 30 | -15.4% |
| 9/28/2006 | 0.25 | 0.12 | 0.11 | 56.0% | 0.13 | 0.05 | 0.02 | 84.6% | 3 | 16 | 12 | -300.0% |
| 10/17/2006 | 0.24 | 0.11 | 0.04 | 83.3% | 0.18 | 0.05 | 0.02 | 88.9% | 13 | 4 | 5 | 61.5% |
| 11/16/2006 | 0.22 | 0.13 | 0.18 | 18.2% | 0.13 | 0.09 | 0.1 | 23.1% | 18 | 11 | 20 | -11.1% |
| 4/11/2007 | 0.33 | 0.12 | 0.11 | 66.7% | 0.09 | 0.07 | 0.04 | 55.6% | 120 | 5 | 7 | 94.2% |
| 12/15/2007 | 0.14 | 0.1 | 0.09 | 35.7% | 0.09 | 0.07 | 0.03 | 66.7% | 22 | 4 | 12 | 45.5% |
| 2/1/2008 | 0.19 | 0.14 | 0.1 | 47.4% | 0.1 | 0.08 | 0.04 | 60.0% | 6 | B.D.L. | 1 | 83.3% |
| 3/4/2008 | 0.15 | 0.1 | 0.1 | 33.3% | 0.11 | 0.07 | 0.05 | 27.3% | 10 | 6 | 6 | 40.0% |
| 3/7/2008 | 0.07 | 0.09 | 0.06 | 14.3% | 0.05 | 0.04 | 0.02 | 60.0% | 14 | 4 | 2 | 85.7% |
| 3/19/2008 | 0.11 | 0.09 | 0.06 | 45.5% | 0.06 | 0.05 | 0.03 | 50.0% | 9 | 4 | 6 | 33.3% |
| Pollutant Loadings (g) and Pollutant Reduction (%) | | | | | | | | | | | | |
| 7/7/2005 | 399.9 | * | * | n.c. | 228.5 | * | * | n.c. | 114244.7 | * | * | n.c. |
| 10/24/2005 | 279.6 | 147.2 | * | n.c. | 93.2 | 88.3 | * | n.c. | 23300.6 | 7849.9 | * | n.c. |
| 1/22/2006 | 301.1 | 45.1 | 29.3 | 90.3% | 82.1 | 12.3 | n.c. | n.c. | 49265.8 | 4098.9 | 7021 | 85.7% |
| 4/21/2006 | 397.4 | * | 26.9 | 93.2% | 264.9 | * | 10.8 | 95.9% | 68875.5 | * | 8064 | 88.3% |
| 9/28/2006 | 159 | 4.1 | * | n.c. | 82.7 | 1.7 | * | n.c. | 1908.3 | 550.8 | * | n.c. |
| 10/17/2006 | 278.7 | 8 | 1.5 | 99.5% | 209 | 3.6 | 0.7 | 99.6% | 15094.1 | 290.1 | 186.3 | 98.8% |
| 11/16/2006 | 855.2 | * | 17.8 | 97.9% | 505.4 | * | 9.9 | 98.0% | 69974.1 | * | 1980.7 | 97.2% |
| 4/11/2007 | 238.7 | 6.9 | 9.3 | 96.1% | 65.1 | 4 | 3.4 | 94.8% | 86812.2 | 285.8 | 592.8 | 99.3% |
| 12/15/2007 | 276.1 | 11.7 | 33.6 | 87.8% | 177.5 | 8.2 | 11.2 | 93.7% | 43384.0 | 469.3 | 4474.9 | 89.7% |
| 2/1/2008 | 163.7 | * | 63.8 | 61.0% | 86.1 | * | 25.5 | 70.4% | 5168.5 | * | 637.8 | 87.7% |
| 3/4/2008 | 92.4 | * | 22.8 | 75.3% | 67.7 | * | 18.2 | 73.1% | 6156.7 | * | 1366.1 | 77.8% |
| 3/7/2008 | 23.7 | 5.3 | 9.2 | 61.3% | 16.9 | 2.3 | 3.1 | 81.9% | 4738.4 | 234.9 | 306.0 | 93.5% |
| 3/19/2008 | 25.2 | 3.6 | 4.5 | 82.1% | 13.7 | 2 | 2.2 | 83.6% | 2058.0 | 159.0 | 449.4 | 78.2% |
| * - Loading not calculated due to inaccurate flow rate measurement B.D.L - Concentration (mg/L) below detection limit (Refer to Table TA-3.18) n.c. = Not Calculated (if concentration was below detectable limit or flow value was inaccurate) | | | | | | | | | | | | |

According to Jones (2009b):

“A Kendall Tau b test was performed on the data to determine trend over time in outfall (Station 3) concentrations and loadings overtime. A significant trend (downward) was only found when analyzing TSS concentration over time ($p = 0.0489$), meaning that the [flow-weighted] concentrations of TSS at the discharge decreased over the time period of the monitoring project.

An ANOVA was performed to compare dry time to outfall concentration, rain quantity to outfall concentration, dry time to outfall loading, and rain quantity to outfall loading. A significant, positive relationship was found for dry time to concentration for total Kjeldahl nitrogen [TKN] ($p = 0.0191$) and total nitrogen ($p = 0.0291$); and rainfall to loading for orthophosphate ($p = 0.0438$), total Kjeldahl nitrogen ($p = 0.0164$), and total nitrogen ($p = 0.0350$).”

[Kendall Tau b test](#)

This statistical analysis measures the association and significance of correspondence between two variables.

Variables are assigned rankings:

-1 = 100% negative association / perfect inversion

0 = No association

+1 = 100 % positive association / perfect agreement

In this case, the statistical test examined performance over time as chemical concentrations vs. sampling date as well as chemical loadings vs. sampling date in a tabular format.

[ANOVA – Analysis of Variance](#)

This analysis represents a collection of statistical models and associated procedures. Generally, an ANOVA examines differences among multiple groups, testing if the means are equal.

In this case, the influence of dry time and rainfall quantity were examined against chemical concentration and loading values.

Snider's Estates (Upper Paint Branch SPA)

Total suspended solids were monitored using grab sampling at Snider's Estates during construction. TSS grab sample data is presented in Table TA-3.10. Only flow leaving Pond 1 was monitored during post-construction. Pond 1 contains a surface sand filter.

An aerial image of the Snider's Estates property is provided in Fig. TA-3.18. The plan views of the SWM treatment train and monitoring locations are provided (Figs TA-3.19 and TA-3.20).




Figure TA-3.18. 2008 aerial image of Snider's Estates.

A total of fifteen storms were captured (Table TA-3.23). Only storms with a return interval >1 year were compared with the TR-20 model expected values.




Figure TA-3.19. Snider's Estates stormwater management facility structure and drainage area detail (Jones & Schreiner 2008).




Figure TA-3.20. Plan view of Snider's Estates SWM with marked sampling locations (Jones & Schreiner 2008). The plan illustrates during construction / pre-conversion sampling points (3) and the discussed post-construction flow monitoring station (Sampling Point 2).

Table TA-3.23. Storm events measured for flow exiting Snider's Estates SWM Pond
1. Events with flow values used to compare with the simulated values are highlighted.

| Date | Quantity of Rain (In.) | Dry Time (Hr.) | Rainfall Duration (Hr.) | Elevated Flow Duration (Hr.) | Average Rainfall Rate (In./Hr.) | Return Interval (Yr.) | Maximum Flow Rate (CFS) |
|------------|------------------------|----------------|-------------------------|------------------------------|---------------------------------|-----------------------|-------------------------|
| 12/23/2004 | 0.87 | 1 | 3.33 | 2.33 | 0.26 | < 1 | 1.386 |
| 1/14/2005 | 1.99 | 1.83 | 6.83 | 6.67 | 0.29 | 1-2 | 4.554 |
| 3/23/2005 | 1.82 | 69.33 | 16.83 | 2 | 0.11 | < 1 | 0.459 |
| 3/27/2005 | 1.00 | 1.17 | 8.5 | 6.83 | 0.12 | < 1 | 1.678 |
| 4/1/2005 | 1.55 | 1.5 | 13.67 | 14.33 | 0.11 | < 1 | 1.96 |
| 6/29/2005 | 1.35 | 10.17 | 3.83 | 1.17 | 0.35 | < 1 | 0.133 |
| 7/7/2005 | 2.93 | 1 | 15.17 | 9.5 | 0.19 | 2 | 4.98 |
| 7/14/2005 | 1.49 | 6.5 | 8.83 | 10 | 0.17 | < 1 | 2.621 |
| 7/16/2005 | 0.51 | 1.67 | 5.5 | 8.17 | 0.09 | < 1 | 2.269 |
| 7/29/2005 | 1.17 | 41.67 | 4.17 | 0.67 | 0.28 | < 1 | 0.271 |
| 10/7/2005 | 6.13 | 1 | 25.5 | 26.17 | 0.24 | 25 | 3.541 |
| 12/15/2005 | 1.25 | 122.5 | 10.25 | 3.17 | 0.12 | < 1 | 0.298 |
| 6/25/2006 | 6.84 | 1.33 | 9.17 | 8.83 | 0.75 | 200 | 10.671 |
| 6/13/2007 | 1.95 | 3.33 | 2.17 | 0.33 | 0.9 | 5 | 0.042 |
| 10/24/2007 | 4.38 | 101.67 | 77.33 | 22.33 | 0.06 | 2 | 0.011 |

TA-3.4.2 Stormceptor® Results

Background

Suggested materials for information on Stormceptor® function and effectiveness:

<http://www.epa.gov/region1//assistance/ceitts/stormwater/techs/stormceptor.html> – Storm Water Virtual Trade Show Stormceptor® (Rinker Materials 2007)

http://www.ceere.org/ees/EES_Publications/step/Stormceptor%20fact%20sheet%20revised%20203.pdf – Stormwater Technology: Stormceptor (STEP 2003)

<http://www.stormwatercenter.net/Practice/120-Stormceptor.pdf> – Performance of a Proprietary Stormwater Treatment Device: The Stormceptor® (RAC 2002)

<http://www.stormceptor.com/> – Stormceptor ® home page (Imbrium Systems Inc. 2007)

<http://www.fhwa.dot.gov/environment/ultraurb/3fs14.htm> – Stormwater Best Management Practices in an Ultra-Urban Setting: Selection and Monitoring Fact Sheet - Manufactured Systems (Shoemaker et al. 2002b)

<http://www.epa.gov/OW-OWM.html/mtb/hydro.pdf> - EPA Storm Water Technology Fact Sheet: Hydrodynamic Separators (US EPA 1999b).

Full citations are provided in the Literature Cited section at the end of this document.

Cloverly Safeway (Upper Paint Branch SPA)

The Stormceptor® functions as additional quality control in the stormwater treatment train utilized at the Cloverly Safeway (Fig. TA-3.21) in Paint Branch SPA. A diagram of Cloverly Safeway stormwater BMPs and sampling locations is provided (Fig. TA-3.22).




Figure TA-3.21. 2008 aerial image of Cloverly Safeway.

Post construction monitoring of stormwater chemistry as it passes through the device was conducted using automated sampling from November 2002 through June 2008. The first storm was collected in May 2003; the final in April 2008. First flush grab samples of total petroleum hydrocarbons (TPH) of influent and effluent as well as continuous monitoring of effluent temperature were also conducted.

Parameters and detection limits are provided in Table TA-3.24 (Jones 2008c). Eleven of the fifteen required storms have been captured; storm characteristics are provided in Table TA-3.25 and loading and concentration data in Table TA-3.26.




Figure TA-3.22. Diagram of Cloverly Safeway SWM BMPs with marked sampling locations (2) (Jones 2008c).

Table TA-3.24. Detection limits and Maryland water quality standards for chemicals monitored at the Cloverly Safeway Stormceptor®.

| Parameter | EPA Method | Detection Limit (mg/L) | Maryland Freshwater Acute Criteria (mg/L) |
|---------------------------------------------|---------------------|------------------------|-------------------------------------------|
| Total Petroleum Hydrocarbons ^(a) | EPA 418.1 | 2 | None |
| Cadmium | EPA 200.8 | 0.0005 | 0.002 |
| Copper | EPA 200.8 | 0.002 | 0.013 |
| Lead | EPA 200.8 | 0.002 | 0.065 |
| Zinc | EPA 200.8 | 0.025 ^(b) | 0.12 |
| Total Suspended Solids ^(c) | EPA 160.2 & SM2540D | 1 | None |

^(a) Collected using grab sample method

^(b) Zinc detection limit varies between 0.005 and 0.025 mg/L

^(c) This parameter was added after the first five storms.

Table TA-3.25. Characteristics of captured storms and measured flow as part of Cloverly Safeway SPA BMP monitoring.

| Storm Date | Rainfall Quantity (in.) | Rain duration (hr.) | Return interval (yr.) | Preceding drying time (h) | Effluent volume (m3) * |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|----------------------------|------------------------------|----------------------------------|-------------------------------|
| 5/9/2003 | 0.31 | 2.0 | < 1 | 23.5 | 137.2 |
| 7/28/2003 | 0.69 | 5.92 | < 1 | 14.83 | 634.2 |
| 4/12/2004 | 1.17 | 12.0 | < 1 | 107 | 947.7 |
| 9/28/2004 | 1.93 | 8.0 | < 1 | 242.75 | 709.8 |
| 12/9/2004 | 0.56 | 7.5 | < 1 | 38.75 | 550.1 |
| 5/23/2005 | 0.75 | 33.67 | < 1 | 73 | 516.1 |
| 10/27/2006 | 1.55 | 31.17 | < 1 | 159.83 | 1098 |
| 11/7/2006 | 1.66 | 26.5 | < 1 | 131.33 | 958.3 |
| 11/15/2006 | 1.75 | 7.92 | < 1 | 68.92 | 662.2 |
| 11/22/2006 | 1.17 | 27.67 | < 1 | 140.33 | 701 |
| 12/22/2006 | 1.05 | 5.0 | < 1 | 214.25 | 693 |
| 12/15/2007 | 0.99 | 13.5 | < 1 | 42.5 | 786.8 |
| 3/4/2008 | 1.03 | 14.25 | < 1 | 246.75 | 603.4 |
| 3/7/2008 | 0.72 | 28.0 | < 1 | 54.25 | 357.8 |
| 4/3/2008 | 0.72 | 20.25 | < 1 | 54.5 | 448.3 |
| * - Flow was only recorded at the downstream station. The quantity of water leaving the Stormceptor© was assumed equal to the quantity entering (Jones 2009b). | | | | | |

Table TA-3.26. Storm concentrations and loadings of chemicals sampled at the Cloverly Safeway Stormceptor®. Loadings were not calculated for total petroleum hydrocarbons (TPH) because this parameter was collected as a “first flush” grab sample. Total suspended solids (TSS) data was not available predating 5/23/2005.

| Storm Event Date | TPH | | Cadmium | | Copper | | Lead | | Zinc | | TSS | |
|-------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------|-----------------------|-----------------------|----------------------|----------------------|--------|----------------------|---------------------|---------------------|----------|---------|
| | Inlet | Outlet | Inlet | Outlet | Inlet | Outlet | Inlet | Outlet | Inlet | Outlet | Inlet | Outlet |
| Analytical Concentration (mg/L) | | | | | | | | | | | | |
| 5/9/2003 | B.D.L. | B.D.L. | B.D.L. | B.D.L. | 0.012 | 0.012 | 0.003 | 0.003 | 0.13 ^(†) | 0.12 ^(†) | n.a. | n.a. |
| 7/28/2003 | B.D.L. | B.D.L. | 0.0061 ^(†) | 0.005 ^(†) | 0.011 | 0.013 ^(†) | 0.01 | 0.161 ^(†) | 0.072 | 0.079 | n.a. | n.a. |
| 4/12/2004 | B.D.L. | B.D.L. | B.D.L. | B.D.L. | 0.008 | 0.008 | 0.003 | 0.002 | 0.068 | 0.057 | n.a. | n.a. |
| 9/28/2004 | B.D.L. | B.D.L. | B.D.L. | B.D.L. | 0.01 | 0.008 | 0.003 | 0.003 | 0.037 | 0.034 | n.a. | n.a. |
| 12/9/2004 | 3 | 3 | B.D.L. | B.D.L. | 0.008 | 0.006 | B.D.L. | B.D.L. | 0.039 | 0.029 | n.a. | n.a. |
| 5/23/2005 | 2 | 7 | B.D.L. | 0.0023 ^(†) | 0.008 | 0.004 | B.D.L. | B.D.L. | 0.062 | 0.034 | 17 | 6 |
| 10/27/2006 | n.s. | n.s. | B.D.L. | B.D.L. | 0.016 ^(†) | 0.006 | 0.004 | B.D.L. | 0.2 ^(†) | 0.05 | 140 | 5 |
| 11/7/2006 | n.s. | n.s. | B.D.L. | B.D.L. | 0.006 | 0.005 | B.D.L. | B.D.L. | 0.057 | 0.074 | 9 | 7 |
| 11/15/2006 | 3 | 5 | B.D.L. | B.D.L. | 0.005 | 0.005 | B.D.L. | B.D.L. | 0.062 | 0.056 | 47 | 20 |
| 11/22/2006 | n.s. | n.s. | B.D.L. | B.D.L. | 0.005 | 0.004 | B.D.L. | B.D.L. | 0.071 | 0.057 | 8 | 8 |
| 12/22/2006 | n.s. | n.s. | B.D.L. | B.D.L. | 0.006 | 0.007 | 0.004 | 0.005 | 0.081 | 0.072 | 10 | 10 |
| 12/15/2007 | n.s. | n.s. | B.D.L. | B.D.L. | 0.0079 | 0.0074 | B.D.L. | B.D.L. | 0.04 | 0.03 | 8 | 8 |
| 3/4/2008 | n.s. | n.s. | B.D.L. | B.D.L. | 0.0041 | 0.005 | B.D.L. | B.D.L. | 0.041 | 0.037 | 16 | 20 |
| 3/7/2008 | n.s. | n.s. | B.D.L. | B.D.L. | 0.0047 | 0.0048 | B.D.L. | B.D.L. | 0.036 | 0.03 | 6 | 11 |
| 4/3/2008 | n.s. | n.s. | B.D.L. | B.D.L. | 0.0058 | 0.0048 | B.D.L. | B.D.L. | 0.035 | 0.024 | 3 | 3 |
| Pollutant Loadings (g) | | | | | | | | | | | | |
| 5/9/2003 | n.c. | n.c. | n.c. | n.c. | 1.6 | 1.6 | 0.4 | 0.4 | 17.8 | 16.5 | n.a. | n.a. |
| 7/28/2003 | n.c. | n.c. | 3.9 | 3.2 | 7 | 8.2 | 6.3 | 102 | 45.7 | 50.1 | n.a. | n.a. |
| 4/12/2004 | n.c. | n.c. | n.c. | n.c. | 7.6 | 7.6 | 2.8 | 1.9 | 64.4 | 54 | n.a. | n.a. |
| 9/28/2004 | n.c. | n.c. | n.c. | n.c. | 7.1 | 5.7 | 2.1 | 2.1 | 26.3 | 24.1 | n.a. | n.a. |
| 12/9/2004 | n.c. | n.c. | n.c. | n.c. | 4.2 | 3.3 | n.c. | n.c. | 20.6 | 16 | n.a. | n.a. |
| 5/23/2005 | n.c. | n.c. | n.c. | 1.2 | 4.1 | 2.1 | n.c. | n.c. | 32 | 17.5 | 8773.1 | 3096.4 |
| 10/27/2006 | n.s. | n.s. | n.c. | n.c. | 17.6 | 6.6 | 4.4 | n.c. | 219.6 | 54.9 | 153724.9 | 5490.2 |
| 11/7/2006 | n.s. | n.s. | n.c. | n.c. | 5.8 | 4.8 | 1.9 | n.c. | 54.6 | 70.9 | 8625.1 | 6708.4 |
| 11/15/2006 | n.c. | n.c. | n.c. | n.c. | 3.3 | 3.3 | n.c. | n.c. | 41.1 | 37.1 | 31122.1 | 13243.4 |
| 11/22/2006 | n.s. | n.s. | n.c. | n.c. | 3.5 | 2.8 | n.c. | n.c. | 49.8 | 40 | 5607.9 | 5607.9 |
| 12/22/2006 | n.s. | n.s. | n.c. | n.c. | 4.2 | 4.9 | 2.8 | 3.5 | 56.1 | 49.9 | 6929.6 | 6929.6 |
| 12/15/2007 | n.s. | n.s. | n.c. | n.c. | 6.2 | 5.8 | n.c. | n.c. | 31.5 | 23.6 | 6294.4 | 6294.4 |
| 3/4/2008 | n.s. | n.s. | n.c. | n.c. | 2.5 | 3 | n.c. | n.c. | 24.7 | 22.3 | 9653.7 | 12067.1 |
| 3/7/2008 | n.s. | n.s. | n.c. | n.c. | 1.7 | 1.7 | n.c. | n.c. | 12.9 | 10.7 | 2147.0 | 3936.1 |
| 4/3/2008 | n.s. | n.s. | n.c. | n.c. | 2.6 | 2.2 | n.c. | n.c. | 15.7 | 10.8 | 1345.0 | 1345.0 |
| B.D.L. - Below Detection Limit (Refer to Table TA-3.24) | | | | | | | | | | | | |
| ^(†) At or above acute criteria value (Refer to Table TA-3.24) | | | | | | | | | | | | |
| n.c. - Not Calculated (Loadings not calculated if concentration was below detectable limit and since TPH was collected as a "first flush" grab) | | | | | | | | | | | | |
| n.s. - Not Sampled | | | | | | | | | | | | |
| n.a. - Not Available | | | | | | | | | | | | |

TA-3.5 Discussion of SPA BMP Effectiveness

There are no technical appendix materials for this section.

Note to Reader

For more information on Section 3 or technical appendix materials, please contact DEP at AskDEP@montgomerycountymd.gov, 240-777-7700.

Page left intentionally blank

Literature Cited

- [CWP] Center for Watershed Protection. 2007. National pollutant removal performance database: version 3. www.stormwater.net
- [GTA] Geo-technology Associates, Inc. 2007. Report of Groundwater and Surface Monitoring: Timbercreek, Montgomery County, Maryland. Prepared for: Elm Street Development, 175 Admiral Cochrane Drive, Suite 112, Annapolis, MD 21401. GTA Project No: 061408.
- Geosyntec Consultants and Wright Water Engineers, Inc. 2007. Overview of performance by BMP category and common pollutant type. International Stormwater Best Management Practices (BMP) Database.
- [Geosyntec Consultants and UWRRC] Geosyntec Consultants and Urban Water Resources Research Council. 2002. Urban Stormwater BMP Performance Monitoring: A Guidance Manual for Meeting the National Stormwater BMP Database Requirements. Prepared in cooperation with United States Environmental Protection Agency, Office of Water, Washington, DC. EPA-821-B-02-001
- Imbrium Systems Inc. 2007. Stormceptor ® home page. <http://www.stormceptor.com/>
- Jones TS 2007. Stormwater Total Suspended Solids Monitoring at Clarksburg Town Center: Third Annual Report. Prepared for Newland Communities by Versar, Inc., Columbia, MD.
- Jones TS 2008a. Stormwater Total Suspended Solids at Stringtown Road (Extended): First Annual Report. Prepared for Biohabitats, Inc., by Versar, Inc., Columbia, MD. June.
- Jones TS 2008b. Water Chemistry Monitoring At the Willow Oaks Stormwater Management Facility: 2008 Annual Report. Prepared for Premiere Homes by Versar, Inc., Columbia, MD. August.
- Jones TS 2008c. Stormwater Effluent Monitoring at Cloverly, Maryland Safeway: 2008 Annual Report. Prepared for Safeway, Inc., by Versar, Inc., Columbia, MD. September.
- Jones TS 2009a. Stormwater Total Suspended Solids at Gateway Commons. Second Annual Report. Prepared for Biohabitats, Inc. by Versar, Inc., Columbia, MD. April.
- Jones 2009b. Memo to R. Gauza: Comments on Snider's Estates, Willow Oaks, and Cloverly Safeway monitoring reports. March 11, 2009.
- Jones 2009. Personal communication. Tom Jones to Rachel Gauza requesting clarification for an estimated flow value in the 2008 Willow Oaks data submission. May 5, 2009.
- Jones TS and SP Schreiner. 2008. Stormwater Total Suspended Solids and Flow Monitoring at Snider's Estates. Prepared for SKW Construction, Inc. by Versar, Inc., Columbia, MD. February.

- [MC DEP] Montgomery County Department of Environmental Protection. 1998. Montgomery County Department of Environmental Protection Best Management Practice Monitoring Protocols. June 1998.
- [MC DPS] Montgomery County Department of Permitting Services. 2007. Montgomery County Sand Filter (MCSF). August 2007.
- Metropolitan Council and Barr Engineering Company. 2001. Chapter 3: Best Management Practices: Surface Sand Filters. In: Minnesota Urban Small Sites BMP Manual: 3-191 – 3-201.
http://www.metrocouncil.org/environment/Watershed/BMP/CH3_STFiltSurfSand.pdf
- [MHG] Macris, Hendricks, & Glascock, P.A. 2009. Stream Temperature and Channel Cross Section Monitoring: Wildcat Branch Tributary Below All Souls Cemetery. June 2008-September 2008 and Final Report. Prepared for: The Catholic Cemeteries of the Archdiocese of Washington, Inc.
- RAC 2002. Performance of a Proprietary Stormwater Treatment Device: The Stormceptor®. In The Practice of Watershed Protection. 2000. T. Schueler and H. Holland, eds. Center for Watershed Protection. Ellicott City, MD. <http://www.stormwatercenter.net/Practice/120-Stormceptor.pdf>
- Rinker Materials 2007. Stormceptor. Storm Water Virtual Trade Show CEIT. New England. US EPA.. <http://www.epa.gov/region1/assistance/ceitts/stormwater/techs/stormceptor.html>
- [RK&K] Rummel, Klepper & Kahl, LLP. 2008. Water quality monitoring report for Briggs Chaney Road Stormwater Management Pond. Montgomery County, Maryland. BCS-2000-13. January 18, 2008.
- [RK&K] Rummel, Klepper & Kahl, LLP. 2009. Personal communication. Justin Reel to Rachel Gauza regarding a table of all major construction activities at US 29 and Briggs Chaney Road Interchange (per the attachment letter dated June 12, 2002). May 6, 2009.
- Shoemaker L, M Lahlou, A Doll, and P Cazenais. 2002a. United States Department of Transportation. Federal Highway Administration. Stormwater Best Management Practices in an Ultra-Urban Setting: Selection and Monitoring, Fact Sheet – Surface Sand Filters. <http://www.fhwa.dot.gov/environment/ultraurb/3fs8.htm>
- Shoemaker L, M Lahlou, A Doll, and P Cazenais. 2002b. United States Department of Transportation. Federal Highway Administration. Stormwater Best Management Practices in an Ultra-Urban Setting: Selection and Monitoring, Fact Sheet Manufactured Systems. <http://www.fhwa.dot.gov/environment/ultraurb/3fs14.htm>
- [STEP] Massachusetts Strategic Envirotechnology Partnership. 2003. Fact Sheet #4, Stormwater technology: Stormceptor (Hydro Conduit, formerly CSR New England Pipe).
http://www.ceere.org/ees/EES_Publications/step/Stormceptor%20fact%20sheet%20revised%202003.pdf.
- Thompson M. 2008. 2008. Gateway Commons: During-Construction Water Quality Monitoring Report. Prepared for Lennar/US Homes by Biohabitats Inc., Baltimore, Maryland. October.

- T.R.S. 2002. Developments in Sand Filter Technology to Treat Stormwater Runoff. In The Practice of Watershed Protection. 2000. T. Schueler and H. Holland, eds. Center for Watershed Protection. Ellicott City, MD.
http://www.cwp.org/Resource_Library/Center_Docs/PWP/ELC_PWP105.pdf
- [US EPA] United States Environmental Protection Agency. Office of Water. 1999a. Storm Water Technology Fact Sheet Sand Filters, EPA 832-F-99-007.
<http://www.epa.gov/owm/mtb/sandfltr.pdf>
- [US EPA] United States Environmental Protection Agency. Office of Water. 1999b. Storm Water Technology Fact Hydrodynamic Separators, EPA 832-F-99-017.
<http://www.epa.gov/OW-OWM.html/mtb/hydro.pdf>
- [US EPA] United States Environmental Protection Agency. Office of Research and Development. 2004. The Use of Best Management Practices (BMPs) in Urban Watersheds, EPA/600/R-04/184. <http://www.epa.gov/nrmrl/pubs/600r04184/600r04184.pdf>

Page left intentionally blank